



**Rolls-Royce**

**Rolls-Royce Corporation  
501-D36**

**COMMERCIAL ENGINE  
BULLETIN  
(CEB)**

**Technical Publications  
Index**

**August 8, 2019**

# Rolls-Royce

## COMMERCIAL ENGINE BULLETIN INDEX

| <u>Bulletin No.</u>      | <u>Subject</u>   | <u>Compliance</u>   | <u>Published</u> | <u>Revised</u>  |
|--------------------------|--|---|------------------|-----------------|
| <b><u>72- ENGINE</u></b> |  |   |                  |                 |
| 72-2001                  | Engine - 6th-Stage Compressor Wheel - Rework   | Recommended at Next Overhaul  | 11-01-66         |                 |
| 72-2002                  | Engine - Thru the Turbine Rotor Venting - Add  | Recommended at Next Overhaul  | 03-01-67         | No. 1, 02-24-69 |
| 72-2003                  | Cancelled Prior to Publication   |   |                  |                 |
| 72-2004                  | Cancelled Prior to Publication   |   |                  |                 |
| 72-2005                  | Cancelled Prior to Publication   |   |                  |                 |
| 72-2006                  | Cancelled Prior to Publication   |   |                  |                 |
| 72-2007                  | Engine - Compressor Diffuser and Secondary Labyrinth Seal Strator -Rework                                | Recommended at Next Overhaul  | 02-10-67         | No. 1, 07-05-68 |
| 72-2008                  | Engine - Oil Filter Check Valve - Modify   | Recommended No Later Than Next Overhaul   | 01-06-67         |                 |
| 72-2009                  | Engine - Rear Turbine Bearing Oil Seal - Rework  | Recommended When Knife Wear or Damage on the 6783785 Seal Exceeds Overhaul Manual Limits            | 04-10-67         | No. 2, 11-14-72 |
| 72-2010                  | Engine - Front Compressor Bearing Separator - Replace  | Comply When Original Separator is Rejected, and Stock of Replacement Bronze Separators is Exhausted | 12-16-66         | No. 2, 12-01-67 |
| 72-2011                  | Cancelled Prior to Publication   |   |                  |                 |
| 72-2012                  | Cancelled Prior to Publication   |   |                  |                 |
| 72-2013                  | Engine - Turbine Rotor Assembly - Modify 1st- and 2nd-Stage to Stalk Blade Configuration                 | Recommended at Next Overhaul  | 11-16-72         |                 |
| 72-2014                  | Engine - Lighthouse O-Ring Grooves - Remachine   | Recommended at Next Overhaul  | 12-27-67         | No. 1, 05-01-68 |
| 72-2015                  | Engine - Turbine Front Bearing Area - Modify   | Recommended at Next Overhaul  | 09-09-69         |                 |
| 72-2016                  | Engine - Turbine Rear Bearing Oil Seal - Rework  | Recommended at Next Overhaul  | 09-05-69         |                 |
| 72-2017                  | Engine - Turbine Vane Support Thru Bolts - Install   | Recommended at Next Overhaul  | 04-21-69         | No. 1, 09-11-70 |
| 72-2018                  | Engine - Accessory Drive Housing Bearing-Baffle - Add  | Recommended at Next Overhaul  | 03-25-69         |                 |
| 72-2019                  | Cancelled Prior to Publication   |   |                  |                 |
| 72-2020                  | Engine - Reduction Gear Main Scavenge Oil Pump - Install Bushings in Cast Iron Body and Plate Assemblies | Install as Required   | 05-15-69         | No. 2, 02-17-70 |
| 72-2021                  | Engine - Reduction Gear Nose Scavenge Oil Pump - Install Bushings in Cast Iron Body and Plate Assemblies | Install as Required   | 05-15-69         | No. 1, 12-04-69 |

# Rolls-Royce

## COMMERCIAL ENGINE BULLETIN INDEX

| <u>Bulletin No.</u>           | <u>Subject</u>   | <u>Compliance</u>   | <u>Published</u> | <u>Revised</u>  |
|-------------------------------|--|---|------------------|-----------------|
| <u>72- ENGINE (Continued)</u> |  |   |                  |                 |
| 72-2022                       | Reduction Gear - Main Oil Pump and Filter Assembly - Rework  | To be Accomplished on a "Use Stock" Basis   | 09-16-71         | No. 1, 03-25-74 |
| 72-2023                       | Cancelled Prior to Publication   |   |                  |                 |
| 72-2024                       | Cancelled Prior to Publication   |   |                  |                 |
| 72-2025                       | Engine - Turbine Front and Rear Bearings - Rework  | Recommended at Next Overhaul  | 09-09-69         |                 |
| 72-2026                       | Engine - Reduction Gear Accessory Drive Bearing Cages - Replace                                    | CANCELLED   |                  |                 |
| 72-2027                       | Engine - Compressor Front Labyrinth Seal - Change Venting System                                   | Recommended No Later Than Next Overhaul   | 06-05-69         |                 |
| 72-2028                       | Engine - Reduction Gear-Propeller Shaft - Rework   | Recommended No Later Than Next Overhaul   | 11-21-69         | No. 1, 03-11-71 |
| 72-2029                       | Engine - Reduction Gear, Locked Races for Main Drive, Rear Carrier and Front Pinion Bearings - Add | Recommended at Next Overhaul  | 05-01-72         | No. 3, 09-25-73 |
| 72-2030                       | Engine - Reduction Gear, Prop Shaft Thrust Bearing - Add Lock for Outer Race                       | Recommended at Next Overhaul  | 05-15-72         |                 |
| 72-2031                       | Reduction Gear - Rear Pinion Bearing and Rear Housing Rework                                       | Recommended at Next Overhaul  | 12-15-71         | No. 2, 01-11-74 |
| 72-2032                       | Engine - Compressor Vane Assembly Air Seals - Replace  | Accomplish when Old Seals must be Replaced and Stock of Silver Seals is Exhausted | 12-14-71         |                 |
| 72-2033                       | Cancelled Prior to Publication   |   |                  |                 |
| 72-2034                       | Diffuser Oil Sump Screen - Install   | To be Accomplished No Later Than Next Overhaul                                    | 09-01-70         | No. 1, 05-01-72 |
| 72-2035                       | Compressor - Diffuser Scavenge Oil Sump Tube - Replace   | To be Accomplished No Later Than Next Overhaul                                    | 08-20-71         |                 |
| 72-2036                       | Reduction Gear-Main Drive Gear Bearing Bore-Enlarge  | CANCELLED, Replaced by CEB 72-2041  |                  |                 |
| 72-2037                       | Engine - Compressor 14th-Stage Wheel - Replace   | Superceded by CEB 72-2087   | 12-20-71         | No. 2, 08-10-99 |
| 72-2038                       | Engine - Inner Rear Exhaust Cone Self-locking Nut - Replace  | Accomplish No Later Than Next Overhaul  | 11-08-71         | No. 1, 01-21-77 |
| 72-2039                       | Cancelled Prior to Publication   |   |                  |                 |
| 72-2040                       | Engine - Accessory Drive Main Pressure and Scavenge Oil Pump Pressure Regulating Valve - Modify    | Suggest on a "Use Stock" Basis  | 02-25-72         | No. 1, 04-13-73 |
| 72-2041                       | Reduction Gear - Main Drive Gear Bearing Bore - Enlarge  | Suggest at Next Overhaul  | 03-25-74         | No. 2, 07-00-90 |
| 72-2042                       | Engine - Reduction Gear, Tachometer Bearing Oil Tube - Add   | Recommended at Next Overhaul  | 10-04-74         | No. 2, 08-28-75 |
| 72-2043                       | Engine Reduction Gear, Main Drive Gear - Molybdenum Spray  | At Next Overhaul  | 05-01-81         | No. 5, 07-15-92 |

# Rolls-Royce

## COMMERCIAL ENGINE BULLETIN INDEX

| <u>Bulletin No.</u>           | <u>Subject</u>  | <u>Compliance</u>   | <u>Published</u> | <u>Revised</u>  |
|-------------------------------|---|---|------------------|-----------------|
| <u>72- ENGINE (Continued)</u> |   |   |                  |                 |
| 72-2044                       | Engine - Reduction Gear, Tachometer Drive Bearing - Replace                       | Recommended at Next Overhaul  | 10-11-74         | No. 1, 04-26-76 |
| 72-2045                       | Engine - Reduction Gear, Sun Gear Flange Hub - Rework                             | Accomplish Concurrently with CEB 72-2041                                  | 04-03-75         | No. 2, 08-20-87 |
| 72-2046                       | Engine - Alternator Shaft - Replace   | Recommended at Next Overhaul  | 11-11-75         | No. 1, 02-27-78 |
| 72-2047                       | Engine - Hydraulic Pump Drive Shaft - Replace                                     | Recommended at Next Overhaul  | 11-11-75         | No. 1, 02-27-78 |
| 72-2048                       | Engine - Reduction Gear, Negative Torque Signal Actuator Rod - Delete             | Suggested at Overhaul at Option of Operator                               | 01-30-78         | No. 2, 08-10-84 |
| 72-2049                       | Engine - Starter Shaft - Replace  | Recommended at Next Overhaul  | 11-24-75         | No. 1, 02-27-78 |
| 72-2050                       | Engine - Reduction Gearbox, Starter Drive Shaft Bearing Flange - Rework           | Recommended at Overhaul   | 03-21-78         | No. 1, 12-14-79 |
| 72-2051                       | Engine - Combustion Chamber Inner Casing Assembly - Rework                        | Suggested at Overhaul as Required   | 12-20-77         |                 |
| A-72-2052                     | Engine - Reduction Gear Propeller Shaft Thrust Nut Cuplock - Add                  | ALERT at Next Overhaul or Repair at a Facility with Overhaul Capabilities | 04-16-82         | No. 1, 06-30-82 |
| 72-2053                       | Engine - Reduction Gear Rear Housing Oil Seal - Add                               | At Next Overhaul  | 07-15-82         | No. 1, 05-20-83 |
| 72-2054                       | Engine - Rear Carrier Bearing Inner Race Locking Keys - Replace                   | At Next Overhaul  | 02-20-81         | No. 1, 09-30-81 |
| 72-2055                       | Engine - Accessory Drive Housing Union - Replace                                  | At Next Overhaul  | 08-31-80         | No. 2, 01-00-89 |
| 72-2056                       | Engine - Power Section Control Assembly, Diffuser Bleed Port Flange Cap - Replace | At Next Overhaul  | 03-16-84         |                 |
| 72-2057                       | Cancelled Prior To Publication  |   |                  |                 |
| 72-2058                       | Engine - Compressor Diffuser Sump Baffle - Add                                    | At Next Overhaul  | 04-22-81         | No. 1, 05-15-81 |
| 72-2059                       | Cancelled Prior to Publication  |   |                  |                 |
| 72-2060                       | Engine - Reduction Gearbox Oil Pump Valve Shaft - Rework and Replace              | At Next Overhaul  | 02-15-85         | No. 1, 08-00-90 |
| 72-2061                       | Engine - Reduction Gear Side Mount Screw Bushings - Replace                       | Customer Option   | 05-23-83         | No. 2, 05-18-01 |
| 72-2062                       | Cancelled Prior to Publication  |   |                  |                 |
| 72-2063                       | Cancelled Prior to Publication  |   |                  |                 |
| 72-2064                       | Engine - Starter Drive Shaft, Internal Spline Lubrication - Add                   | At Next Overhaul  | 03-14-85         |                 |
| 72-2065                       | Engine - Combustion Liner Crossover Tube Clamps - Add                             | At Next Overhaul  | 10-01-84         |                 |
| 72-2066                       | Engine - Turbine Assembly, Rear Bearing Support Cone Assembly - Service Repair    | At Overhaul on an "As Required" Basis                                     | 03-13-85         | No. 2, 9-15-98  |

# Rolls-Royce

## COMMERCIAL ENGINE BULLETIN INDEX

| <u>Bulletin No.</u>           | <u>Subject</u>   | <u>Compliance</u>   | <u>Published</u> | <u>Revised</u>  |
|-------------------------------|--|---|------------------|-----------------|
| <u>72- ENGINE (Continued)</u> |  |   |                  |                 |
| 72-2067                       | Cancelled Prior to Publication   |   |                  |                 |
| 72-2068                       | Engine - Power Section and Reduction Gear Main Oil Filter Cover Assemblies - Puller Holes- Add | "As Required" at Next Overhaul  | 08-10-84         |                 |
| 72-2069                       | Engine - Reduction Gear Assembly, Prop Shaft Thrust Nut Lock Cup Lock - Rework                 | At Next Overhaul  | 10-05-84         |                 |
| 72-2070                       | Engine - Spline-Turbine, Starter Shaft 3/4 In. Drive - Replace                                 | Comply at Earliest Opportunity  | 03-20-86         |                 |
| 72-2071                       | Engine - Turbine Vibration Pickup Mount - Add  | At Next Overhaul  | 07-14-86         | No. 3, 08-23-99 |
| 72-2072                       | Engine - Reduction Gear Assembly Tachometer Drive Idler Gear - Shot Peen                       | "As Required" at Next Overhaul  | 12-22-86         | No. 3, 10-23-00 |
| 72-2073                       | Reduction Gear Assembly Safety Coupling Intermediate - Inspect                                 | Recommended at Next Overhaul  | 09-15-91         |                 |
| 72-2074                       | Engine - Inspection of Rear Compressor Bearing (6846298)                                       | Immediately   | 06-11-92         |                 |
| 72-2075                       | Engine - Reduction Gearbox Main Drive Gear, Serviceability Criteria                            | At Next Overhaul or Major Repair  | 09-30-92         | No. 1, 02-12-01 |
| 72-2076                       | Engine - 15 Micron Pressure Oil Filter, Installation   | Replace on Attrition Basis Repair   | 03-31-95         |                 |
| 72-2077                       | Engine - 5th-Stage Compressor Blades Inspection Requirements                                   |   | 09-30-93         |                 |
| 72-2078                       | RGB - Planet Journal Plugs   | Recommended at Next Shop Visit  | 08-16-01         |                 |
| 72-2079                       | Engine - Air Inlet Housing, Inspection/Rework  | Next Shop Visit or When Engine is Removed for Maintenance                       | 03-15-92         | No. 4, 03-11    |
| 72-2080                       | Rear Carrier Bearing (P/N 6871650) Inspection  | Recommended at Next Overhaul or Major Repair                                    | 01-26-98         | No. 1, 12-10-02 |
| 72-2081                       | Approved Liquid Gas Path Cleaners - Motoring Wash  | Comply at Earliest Opportunity  | 02-01-98         | No. 2, 08-25-14 |
| 72-2082                       | Compressor Inlet Blockage  | Recommended at Intermediate and Overhaul Maintenance Activities                 | 02-01-98         |                 |
| 72-2083                       | Oil Foaming  | Recommended at Organizational, Intermediate and Overhaul Maintenance Activities | 02-01-98         | No. 1, 04-06-18 |
| 72-2084                       | T56/501D Solid State Amplifier Adjustment  | Recommended at Adjustment of TD Amplifier                                       | 01-26-98         | No. 1, 06-01-98 |
| 72-2085                       | Compressor Air Inlet Housing Inspection/Rework   | CANCELLED, Superseded by CEB 72-2079  |                  |                 |
| 72-2086                       | Rear Compressor Bearing P/N 23057662   | Recommended at Next Shop Visit  | 05-14-99         | No. 1, 05-05-00 |
| 72-2087                       | TorqueMeter Mid-Bearing PN 23064888  | Recommended at Next Shop Visit  | 05-14-99         | No. 2, 03-14-11 |

# Rolls-Royce

## COMMERCIAL ENGINE BULLETIN INDEX

| <u>Bulletin No.</u>                | <u>Subject</u>  | <u>Compliance</u>   | <u>Published</u> | <u>Revised</u>  |
|------------------------------------|---|---|------------------|-----------------|
| <u>72- ENGINE (Continued)</u>      |   |   |                  |                 |
| 72-2088                            | 14th Stage Compressor Wheel<br>Silver/Indium Plating Replacement  | Recommended at Next Overhaul  | 08-10-99         | No. 2, 07-20-00 |
| 72-2089                            | New Prop Shaft Seal Kit<br>(P/N 23053159)   | Recommended at Next Shop<br>Visit                                       | 09-11-00         |                 |
| 72-2090                            | Custom 450 1st-stage Compressor<br>Vane Assembly, P/N 6878361   | Optional  | 05-12-08         |                 |
| 72-2090                            | Reduction Gearbox (RGB) Carrier Oil<br>Delivery Flange & Sun Gear Lube<br>Tube Assembly Rework                                | Recommended at Next Shop<br>Visit                                       | 05-12-08         |                 |
| 72-2090                            | Reduction Gearbox Assy - Pinion<br>Shaftgear Inspection   | Recommended at Next Shop<br>Visit                                       | 04-30-10         |                 |
| 72-2095                            | Reduction Gearbox Assembly- Two-Piece Starter Driv Shaft Seal   |   | 01-29-16         |                 |
| 72-2098                            | Engine - Suspect External Scavenge<br>Oil Pump Assembly P/N 6846567<br>Inspection for End Face Clearance of<br>Internal Gears | Recommended   | 04-09-14         | No. 1, 08-22-14 |
| <u>73- ENGINE FUEL AND CONTROL</u> |   |   |                  |                 |
| 73-2001                            | Engine Fuel and Control - Fuel<br>Control Thermostat - Replace  | Recommended When Stock of<br>330003 Thermostat Assembly<br>is Exhausted | 09-27-76         |                 |
| 73-2002                            | Engine Fuel and Control - Speed<br>Sensitive Control Drive Shaft,<br>Nylon Sleeve - Add                                       | Recommended at Next<br>Overhaul   | 02-12-70         |                 |
| 73-2003                            | Engine Fuel and Control -<br>Rework of P <sub>2</sub> Lever   | Recommended at Next<br>Overhaul   | 08-28-68         |                 |
| 73-2004                            | Engine Fuel and Control -<br>Thermostat Probe Mounting  | Recommended at Next<br>Overhaul   | 01-23-69         | No. 2, 02-05-75 |
| 73-2005                            | Engine Fuel and Control - Front<br>Body Fuel Seal Retaining Web-<br>Rework  | At Overhaul As Required   | 01-09-70         |                 |
| 73-2006                            | Engine Fuel and Control Metering<br>Valve Collar - Rework   | At Overhaul As Required   | 01-09-70         |                 |
| 73-2007                            | Engine Fuel and Control - Speed<br>Sensitive Drive Coupling - Replace   | At Overhaul on a "Use Stock"<br>Basis                                   | 08-15-73         | No. 1, 07-15-80 |
| 73-2008                            | Engine Fuel and Control - Fuel<br>Metering Valve Spring Nylon<br>Snubbing Block - Add   | At Next Overhaul  | 10-04-76         |                 |
| 73-2009                            | Engine Fuel and Control Fuel<br>Control Thermostat Capillary<br>Tube - Replace  | Accomplish on a "Use Stock"<br>Basis                                    | 11-13-79         |                 |
| 73-2010                            | Engine Fuel and Control - Elect<br>Temperature Datum Control Amp<br>Chopper - Replace   | Recommended When Stock of<br>Mechanical Choppers are<br>Exhausted       | 10-24-79         |                 |
| 73-2011                            | Fuel Nozzle Holding Fixture -<br>Rework   | At First Opportunity  | 08-15-78         |                 |
| 73-2012                            | Cancelled Prior to Publication  |   |                  |                 |

# Rolls-Royce

## COMMERCIAL ENGINE BULLETIN INDEX

| <u>Bulletin No.</u>                            | <u>Subject</u>  | <u>Compliance</u>                                   | <u>Published</u> | <u>Revised</u>  |
|--|---|---|------------------|-----------------|
| <u>73- ENGINE FUEL AND CONTROL (Continued)</u> |   |   |                  |                 |
| 73-2013  | Engine Fuel and Control -<br>Anti-Icing Air Tube Probe - Replace                                  | At Next Overhaul                                    | 03-05-88         | No. 1, 09-01-90 |
| 73-2014  | Engine Fuel and Control - Thrust<br>Sensitive System Carbon Switch<br>Assembly, Wire Clamps - Add | No Later Than Next Overhaul                         | 09-30-86         | No. 2, 06-00-88 |
| A-73-2015                                      | Engine Fuel and Control Thrust<br>Sensitive System Assembly -<br>Functional Check                 | Refer to Bulletin                                   | 06-30-86         | No. 1, 12-22-86 |
| 73-2016  | Engine Fuel and Control -<br>Shrouded Anti-Ice Probe - Rework                                     | To be Accomplished<br>Concurrently with CEB 73-2013 | 07-00-88         | No. 2, 03-31-08 |
| 73-2017  | Cancelled Prior To Publication  |   |                  |                 |
| 73-2018  | Cancelled Prior to Publication  |   |                  |                 |
| 73-2019  | Turbine Engine Main Fuel Control,<br>New Service Limits for Governor<br>Shafts                    | Recommended at Next Overhaul<br>or Repair           | 09-01-90         | No. 2, 05-19-98 |
| 73-2020  | Fuel Nozzle Upgrade Instructions  | At Next Overhaul                                    | 09-25-06         | No. 2, 10-27-14 |
| 73-2021  | New Fuel Nozzle Body, P/N 154866  | At Next Overhaul                                    | 09-25-06         |                 |
| <u>74- IGNITION</u>                            |   |   |                  |                 |
| 74-2001  | Ignition - New Solid State Ignition<br>Relay P/N 23090200   | Optional  | 08-22-14         |                 |
| <u>75-AIR</u>                                  |   |   |                  |                 |
| 75-2001  | Air-Speed Sensing Valve Air Line<br>Filter - Replace  | Recommended at Next<br>Overhaul                     | 05-12-67         |                 |
| 75-2002  | Cancelled Prior to Publication  |   |                  |                 |
| 75-2003  | Cancelled Prior to Publication  |   |                  |                 |
| <u>77-ENGINE INDICATING</u>                    |   |   |                  |                 |
| 77-2001  | Engine Indicating - Thermocouple<br>Harness - Replace   | Recommended at Next<br>Overhaul                     | 02-22-68         |                 |
| 77-2002  | Torquemeter Indicator Assembly<br>- Modification  | Recommended No Later Than<br>Next Overhaul          | 11-05-69         |                 |