



Rolls-Royce

**Rolls-Royce Corporation
T56-A-14LFE**

**COMMERCIAL SERVICE
LETTER
(CSL)**

**Technical Publications
Index**

November 1, 2023

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Subject</u>	<u>Published</u>	<u>Revised</u>
4001	Cancelled prior to publication		
4002	Approved Lubricants – Engine Oil System	02-16-73	No. 9, 09-09-19
4003	Magnetic Plugs 6792118, 6822092, and 6822222	01-29-79	
4004	Temp Datum Valve Motor Retaining Screw (Retorque)	02-06-79	No. 1, 11-21-80
4005	Fire Extinguisher Material (Cleaning)	08-30-79	No. 2, 02-27-80
4006	Compressor Inlet Blockage	08-31-79	No. 3, 02-03-99
4007	Engine Inspection Requirements When Exposed to Volcanic Ash	06-02-80	
4008	Unexplained Loss of Propeller Oil (Hamilton Standard Propeller Installation)	07-15-80	
4009	Oil Leakage – Accessory Drive Housing Fitting	02-12-81	No. 1, 02-28-91
4010	Inspection of Prop Shaft Thrust Nut Lock Installation On Power Plant Installations with Hamilton Standard Props	07-21-78	No. 1, 07-30-81
4011	Use of Military Surplus and Unapproved Parts in Rolls-Royce Commercial Engines	07-10-75	No. 4, 05-10-01
4012	Engine Performance – Maintenance Ground Check Procedure 501-D22A, 501-D22C, T56-A-14LFE and T56-A-15LFE Engines	Cancelled	Ref. CSL 4037
4013	Cancelled Prior to Publication		
4014	Cancelled Prior to Publication		
4015	Allison T56 LFE Engines – General Information	07-15-83	
4016	Authorized Engine Overhaul and Repair Centers	07-31-74	No. 29, 05-31-19
4017	Reduction Gear Prop Shaft Seal, 6851491	03-28-85	
4018	Propeller Retaining Nut Torque	06-15-86	No. 5, 06-30-08
4019	Identification of Allison Power Parts (APP)	08-15-85	
4020	Reduction Gear Propeller Shaft Assembly, 6875798	02-26-86	
4021	Return of Parts for Field Investigation at Allison or Allison or Allison – Approved Distributor or Maintenance and Overhaul Centers	02-28-86	
4022	Scavenge Oil System Test Kit 23037932 Availability	Cancelled	
4023	Cancelled Prior to Publication		
4024	Seal Shelf Life – Age Control	07-00-89	No. 1, 04-00-90
4025	Operation of Bendix Fuel Control and Power Turbine Governors Exposed to Fire or Severe Overtemperature	12-01-89	No. 1, 04-00-90
4026	Improved Anti-Icing Air Valve Seals	08-00-89	No. 1, 01-31-94
4027	T56/501D, Series II, III, Engine Life Limited Parts	12-10-65	No. 22, 08-06-15
4028	Reduction Gear Assembly Splitline Torque Procedure	02-28-91	
4029	Excessive Oil Consumption In-flight and/or on Ground	02-28-91	
4030	Replacement Battery for Temp Trim System Test Set 6799111 and 6799215	06-01-90	
4031	Rolls-Royce Parts Ordering Process	06-28-95	No. 2, 03-11-02
4032	Introduction of New Compressor 5th-and 10th-Stage Bleed Gaskets	07-06-95	
4033	Operation and Maintenance of the T56 Thermocouple	07-06-95	

June 1, 1993

Revised November 1, 2023

T56-A-14LFE INDEX

PAGE 1 OF 3

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Subject</u>	<u>Published</u>	<u>Revised</u>
A4034	Alert - Severe Over-Temperature Operation	07-26-95	
4035	Power Section, RGB Oil Pressure Limitations	07-31-95	No. 1, 05-05-99
4036	Technical Manual Current Issue Status Report	Cancelled	
4037	Engine Performance Ground Check Procedure Performance Calculations and Trending Software and Support Equipment Release	11-29-96	No. 7, 07-13-15
4038	Fuel Nozzle Bolt Lubricant	09-25-95	
4040	Prop Shaft Cleaning at Installation	09-25-95	
4041	Engine Fuel Nozzle Cleaning	09-25-95	
4042	Paralleling Valve, Fault Isolation	09-29-95	
4043	Disabling the Fuel Enrichment System	11-30-96	No. 1, 11-15-97
4044	Turbine Module Installation Kit	07-24-95	No. 2, 12-01-97
4045	Certification Status, Allison 501-D36 Engine	02-28-97	
4046	Updated Compressor Inlet Temperature (CIT) Correction Charts	01-26-98	No. 3, 08-20-14
4047	Compressor Inlet Sensing Probe Torque	11-15-97	
4048	Overboard Fuel Venting	12-01-97	
4049	T56/501D Series III 2nd-stage Wheel Measurement	12-15-97	
4050	T56/501D Series II and III Unexplained Oil Loss	05-20-98	
4051	Operation and Maintenance of T56/501D Engines in Erosive Environments	02-23-98	
4052	T56/501D Engine Overtorque	01-26-98	
4053	Allison T56-LFE Engine Information	11-15-97	
4054	Use of Low Speed Ground Idle	01-26-98	
4055	T56/501D Pinion Bearing Limits	01-12-98	
4056	T56 Engine Torching at High Power Settings	03-15-98	
4057	Titanium Nitride (TiN) Coated Compressor Blades	03-09-98	
4058	Allison Repaired Combustion Liner Exchange	02-03-99	06-30-17
4059	Water Quality for Engine Wash/Rinse	01-28-99	
4060	Alternates For ODC/EPA-17 Chemicals	09-23-99	
4061	P/N 23009988 2nd Stage Turbine Vane, Step In Forward Vane Slot	10-15-99	
4062	Alternate for Acti-Thane WC-100 Paint	04-05-00	
4063	New Spring for use in Fuel nozzle Assemblies	05-17-00	
4064	Reduction Gearbox (RGB) - Main Drive Gear Bearing Failures	05-10-01	
4065	Warranty Policy GT-8545 (B) Dated 5/00	02-08-01	
4066	P/N 6847349 Turbine Inlet Case Machining Condition	06-25-01	No. 1, 06-28-01
4067	Shipment of Fuel System Components	10-25-01	
4068	Visual Color Change of 3rd-Stage Turbine Blade, P/N 6875243	12-03-01	
4069	Spare Part Warranty Return Process	02-01-02	

June 1, 1993

Revised November 1, 2023

T56-A-14LFE INDEX

PAGE 2 OF 3

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Subject</u>	<u>Published</u>	<u>Revised</u>
4070	Procurement of Publications	10-22-76	No. 4, 03-11-02
4071	Thermocouple Assembly, P/N 23075403	03-12-03	No. 1, 05-26-05
4072	P/N 6852412, 4th-Stage Turbine Blade	08-31-04	
4073	New 1st-Stage Turbine Blade P/N 23062421 Visual Differences From The Original P/N 23065975	07-12-05	
4074	To Clean the Engine of Bird Residue After a Bird Strike	02-26-07	
4075	Inspection Required Following Metal Generating Failures	05-12-09	
4076	Use of Accident - Incident Hardware	03-07-11	
4077	Black Oxide Removal	06-29-17	
4078	Repair of 2nd-, 3rd-, and 4th-stage Turbine Vane Inner Diameters	05-23-11	
4079	Jet Fuel Contaminated with Fatty Acid Methyl Ester (FAME)	01-30-12	
4080	Loctite Plastic Gasket 568 (Loctite 68 or Loctite 56841) Replacement	08-20-12	
4081	Compressor Wheel Corrosion Inspection Limits	10-22-15	
4082	T56 LFE Series 3.5 Engine Life Limited Parts	04-09-21	
4083	Part Marking Definition for the 23086350 1st-stage Turbine Saddle Vane Change	10-13-22	
■ 4086	Dry Film Lubricant SurfKote Discontinued, Alternate DFL	10-24-23	

