

Rolls-Royce Corporation T56-A-15LFE

COMMERCIAL OVERHAUL INFORMATION LETERS (COIL)

Technical Publications Index

August 8. 2019

Rolls-Royce

COMMERCIAL OVERHAUL INFORMATION LETTER INDEX

| COIL No. | <u>Subject</u> | <u>Published</u> | Revised |
|----------|---|------------------|-----------------|
| 1501 | Fluorescent Magnetic Particle Inspection of Engine Control Rods and Links | Cancelled | |
| 1502 | Cancelled Prior to Publication | | |
| 1503 | Overhaul of Fuel Nozzle Spray Tips | Cancelled | |
| 1504 | 1st- and 2nd-Stage Turbine Axial Vane Clearance - Model 501-D22A, D22C, and T56-A-15LFE | Cancelled | |
| 1505 | Actithane WC 100 Paint | Cancelled | |
| 1506 | Outer Combustion Case Inspection | Cancelled | |
| 1507 | Permanent Resin Coating - AMS 3135 | Cancelled | |
| 1508 | Turbine Guide Vane and Seal Support Inspection and Repair Procedures | Cancelled | |
| 1509 | Cancelled Prior to Publication | | |
| 1510 | Material Identification of Commercial Turbine Blades For Alpak Purposes | 08-25-78 | |
| 1511 | Cancelled Prior to Publication | | |
| 1512 | Cancelled Prior to Publication | | |
| 1513 | Reduction Gearbox Negative Torque Signal (NTS) Plunger Bore Repair | 04-25-80 | |
| 1514 | Cancelled Prior to Publication | | |
| 1515 | Rear Turbine Bearing Installation | 02-12-80 | |
| 1516 | Shot Peening of 1st Stage Compressor Wheels, 6841211, 6871321, 6829661, 6844081 6805701, and 6789681 | 12-21-84 | No. 6, 07-01-14 |
| 1517 | Pinion Shaftgear Assembly MPI Inspection | 03-00-89 | |
| 1518 | Critical Shafting Inspection for Grinding Burns | 02-28-91 | |
| 1519 | Coordinator Control - Assembly Grease Change | 02-28-91 | |
| 1520 | 3rd-Stage Turbine Wheel Inspection 6845593 (Series III) | 01-30-93 | |
| 1521 | Planet Gear and Bearing Assembly, Replaceable Roller Sets | 11-30-93 | No. 1, 07-08-03 |
| 1522 | Cancelled Prior To Publication | | |
| 1523 | Non-AEP Coating - 2nd Stage Blade 6898062 | 08-31-95 | |
| 1524 | Improved Starting Fuel Schedule | 11-15-96 | |
| 1525 | Wide Rim, 1st to 2nd Stage Turbine Spacer Rework and Turbine Clamp Bolt Torque Change | 10-31-96 | No. 2, 01-15-02 |
| 1526 | Fuel Control Speed Piston O-Ring Seal | 12-08-97 | No. 2, 06-01-01 |
| 1527 | Series III 1st Stage Turbine Saddle Vane - Broken Tang | 02-01-98 | |
| 1528 | Metco 445NS Replacement for Sprabronze AA | 12-08-97 | No. 3, 07-11-03 |
| 1529 | Reduction Gearbox Cracking in the Eyebolt Boss and Mounting Pad Area | 02-23-98 | No. 2, 05-28-04 |
| 1530 | Second and Third Stage Turbine Vane Honeycomb Replacement | 03-01-99 | No. 2, 11-15-06 |
| 1531 | Rear Carrier Cage Bolt Torque | 12-15-98 | |
| 1532 | Reduction Gear Housing Starter Drive Shaft Magnetic Oil Seal , Removal, Disassembly Cleaning, Inspection, Assembly and Installation | 03-15-99 | No. 1, 09-15-03 |

T56-A-15LFE INDEX

Rolls-Royce

COMMERCIAL OVERHAUL INFORMATION LETTER INDEX

| COIL No. | Subject | <u>Published</u> | Revised |
|----------|---|------------------|---------------------|
| 1533 | Torquemeter Housing Plate Change From Cadmium To Nickel | 02-10-99 | |
| 1534 | Rear Turbine Bearing Support Weld Wire and Annealing Process | 09-13-99 | |
| 1535 | Replacement for Brayco 814 Oil | 04-05-00 | |
| 1536 | New Fuel Control Assembly, P/N 6892328-Improved Starting Fuel Schedule and Speed Piston O-ring Seal Replacement | 08-04-00 | No. 1, 07-03-02 |
| 1537 | 14th - Stage Compressor Wheel - Alternative Repair Method for Hub OD/ID - Rework | 01-08-04 | |
| 1538 | Inner Rear Exhaust Cone-Anti-Rotation Slot Inspection/Repair | 12-12-00 | |
| 1539 | Improved Bearing Designs Released to T56/501D Series I, II, III Engine Models | 05-18-01 | No. 1, 10-19-05 |
| 1540 | Compressor Case Silicone Resin Removal-Rework | 12-15-00 | |
| 1541 | Anti-Ice Solenoid Valve, P/N 23052049 | 01-17-01 | |
| 1542 | Cancelled Prior to Publication | | |
| 1544 | Fuel Nozzle Overhaul Procedures | 12-12-01 | No. 1, 01-10-02 |
| 1545 | Compressor Blade Surface Finish, Stages 10-14 | 01-29-02 | |
| 1546 | Metco 444, Alternate Method to Metcoloy 2 (Metco 2) | 07-22-03 | |
| 1547 | Compressor Wheel Plating - Hydrogen Embrittlement Relief | 01-23-04 | Reissue 02-04-04 |
| 1548 | Approval of Metco 73FNS-2 or Metco 72F Plasma Spray as Alternate Repairs for: Vane and Seal Support Internal Diameter (6870406) Inner Combustion Casing Piston Ring Grooves (6789860) | 10-07-04 | |
| 1549 | Propeller Thrust Nut, HVOF Tungsten Carbide Coated Sealing Surface | 10-07-04 | |
| 1550 | Approval of Alternate Materials for BUNA-N Rubber on the Air Inlet Housing | 10-06-04 | |
| 1551 | Cast Turbine Front Bearing Support Repair P/N 23071468 | 01-18-05 | No. 3, 09-22-16 |
| 1552 | Engine - Compressor Wheel Rework, Blade Retention | 04-06-05 | |
| 1553 | Compressor Tie Bolt Plating | 03-02-05 | |
| 1555 | P/N 23009372 Turbine Vane Case - Add Chamfer to Inner Vane Slots | 04-21-08 | |
| 1556 | Compressor Case Blade Track: Application of XPT 268 and Alternates Coatings | 10-06-08 | No.1, 01-29-19 |
| 1557 | Inspection of Oil Jet Nozzle, PN 23055584, At Reduction Gearbox Depot Visit | 03-17-17 | |