

# Rolls-Royce Corporation M250-B17

# COMMERCIAL SERVICE LETTER (CSL)

# Technical Publications Index

March 3, 2020

CSL No.	<u>Title/Description</u>	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1001	M250 Authorized Maintenance Centers (AMC's), Publications, Rolls-Royce Telephone Contacts, Warranty, Training, and Unapproved Parts	Reissue 03-31-97	11	06-11-18
TP 1002	Approved Lubricants-Engine Oil System	Cancelled-Ref: Ops. And Maint. Manual		
TP 1003	Fuels Approved for use in 250 Series Engines	Cancelled-Ref: Ops. And Maint. Manual		
TP 1004	250-B17 Time Between Overhauls	Cancelled-Ref: Ops. And Maint. Manual		
TP 1005	250-B17 Life Limited Parts	Cancelled-Ref: Ops. And Maint. Manual		
TP 1006	O-Ring Added Between Oil Filter Element and Standpipe	Cancelled-Ref: Illus. Parts Catalog		
TP 1007	AVGAS Mixture using 100/130 Aviation Gasoline with Commercial Jet A Turbine Fuel for Cold Weather Operation	Cancelled-Ref: Ops. And Maint. Manual		
TP 1008	Maximum Continuous Power and Maximum Cruise Power Ratings	02-13-73		
TP 1009	Water Washing the Compressor in Cold Weather	Cancelled-Ref: Ops. And Maint. Manual		
TP 1010	Starter Generator and Starter Generator Gearshaft Mating Spline Wear	Cancelled-Ref: Ops. And Maint. Manual		
TP 1011	Extreme Turbine Outlet Temperature Effects on Turbines	09-30-73		
TP 1012	Single-Element Fuel Pump Shouldered Drive Shaft Inspection	Cancelled-Ref: Ops. And Maint. Manual		
TP 1013	Model 250 Engine Log Books	Cancelled 03-24-08		
TP 1014	250 Series Engines - Cost Effect of Modular Overhaul	Cancelled-Ref: Ops. And Maint. Manual		
TP 1015	250-B17B, -B17C, -B17D Time Between Overhauls	Cancelled-Ref: Ops. And Maint. Manual		

#### COMMERCIAL SERVICE LETTER INDEX

CSL No.	<u>Title/Description</u>	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1016	250-B17B, -B17C, -B17D Engine Life Limited Parts	Cancelled-Ref: Ops. And Maint. Manual		
TP 1017	Bleed Valve Cleaning	Cancelled-Ref: Ops. And Maint. Manual		
TP 1018	Model 250 Reporting	02-20-75	8	02-07-11
TP 1019	Use of Unapproved Parts, Engines, Major Modules, or Piece Parts That May Have Been in Long Term Storage in Rolls-Royce Commercial Engines	07-10-75	7	02-12-02
TP 1020	Noisy 250 Series Engine Fuel Pumps	11-26-75	4	06-08-04
TP 1021	Rotating Balance of the Engine and Propeller Assembly	Cancelled-Ref: Ops. And Maint. Manual		
TP 1022	Replacement Interval of Fuel Inlet Filter Strainer in Bendix Fuel Control	Cancelled-Ref; Ops. And Maint. Manual		
TP 1023	Cancelled Prior to Production			
TP 1024	250 Compressor Erosion Inspection	Cancelled-Ref: Ops. And Maint. Manual		
TP 1025	Cancelled Prior to Publication			
TP 1026	Engine Operating Procedures	Cancelled-Ref: Ops. And Maint. Manual		
TP 1027	Cancelled Prior to Publication			
TP 1028	Field Cleaning Procedure Relative To Carbon Caused Turbine $\rm N_2$ Lock up - All Series I and II Model 250 Engines	Cancelled-Ref: Ops. And Maint. Manual		
TP 1029	Cancelled Prior to Publication			
TP A-1030	Power Turbine Outer Coupling Nut Inspection	10-27-76	5	07-22-94
TP 1031	Engine N <sub>2</sub> Operating Speed Recommendation	Cancelled-Ref: CEB-A-1146		
TP 1032	Part No. 6853282 And 6887113 Third-Stage Turbine Wheel Replacement Schedule for Casting Sub-surface Porosity	Cancelled		
TP 1033	Cancelled Prior to Publication			
TP 1034	Part No. 6887113 and 6888633 Third-Stage Wheel $\rm N_2$ Operating Restriction and Alternatives - Overview	Cancelled-Ref: CEB-A-1146		

#### COMMERCIAL SERVICE LETTER INDEX

CSL No.	Title/Description	Date <u>Published</u>	Revision Number	Date <u>Revised</u>
TP A-1035	Part No. 6871492 Beta Valve Adapter or Prop Oil Plug	06-17-77		
TP 1036	DDA Model 250 Customer Questionnaire	Cancelled		
TP 1037	Application of Sealing Compound to the Nozzle of the Compressor Bleed Valve Assembly	Cancelled		
TP 1038	Limited Take-off Power - Fuel Control Maximum Flow Adjustment	11-30-77		
TP 1039	Oil Foaming and Oil Pressure Fluctuations	03-09-78		
TP 1040	Gearbox, Wet Spline Starter-Generator Gearshaft (Customer Option)	03-31-78		
TP 1041	Troubleshooting the Start Derich System of 250-B17/-B17B Bendix Fuel Control	06-16-78	1	06-26-79
TP 1042	New Coordinator Beta Control Lever Rigging Procedures	Cancelled-Ref: Ops. And Maint. Manual		
TP 1043	Compressor Case Bolt Tightening Sequence	Cancelled-Ref: Ops. And Maint. Manual		
TP 1044	Inspection of <u>FACET</u> Low Pressure Fuel Filter Element (DDA P/N 6895177; Kit P/N 6895028)	Cancelled		
TP 1045	Cancelled Prior to Publication			
TP 1046	Turbine to Compressor Coupling	Cancelled-Ref: Ops. And Maint. Manual		
TP 1047	Cancelled Prior to Publication			
TP 1048	Compressor Case Stator Vane to Rotor "Rub"	03-30-79		
TP 1049	Air Purge of Low Pressure (LP) Fuel Filter for Single Element Fuel Pumps on Boost Pump Equipped Aircraft	Cancelled-Ref: Ops. And Maint. Manual		
TP 1050	Lubrication System Troubleshooting	06-07-79	7	09-14-09
TP A-1051	Third-Stage Turbine Wheels, Full or Center Slot, Blade Shroud Configuration, Replacement After Hot Start - Series II Engines	07-15-79	4	09-01-94
TP 1052	Use of Silicone Base Molydisulfide and Nickel Base Anti-Seize Compounds	07-06-79	2	02-15-80
TP 1053	Recall of "Prist" Packaged in Cans Manufactured by Continental Can Company	Cancelled		
TP 1054	Cancelled Prior to Publication			

CSL No.	Title/Description	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1055	Purchase of Detroit Diesel Allison Commercial Model 250 Engines	07-12-79		
TP 1056	Fuel Pump Filter By-Pass Valve - Periodic Operational Check	Cancelled-Ref: Ops. And Maint. Manual		
TP 1057	Oil System Inspection and Maintenance on Model 250-C20B, -C20F, -B17B, and-B17C Engines	Cancelled-Ref: Ops. And Maint. Manual		
TP 1058	Fire Extinguisher Material (Cleaning)	09-28-79	1	12-1-80
TP 1059	Fully Slotted Third-Stage Turbine Wheels, P/N 6887113	Cancelled-Ref: CEB-A-1146		
TP 1060	Engine Oil Change Time Interval	Cancelled-Ref: Ops. And Maint. Manual		
TP 1061	Special Inspections for Engines Operated in Volcanic Ash	06-02-80	5	01-05-07
TP 1062	Compressor Case-Sealing of Cracked Plastic Liner	Cancelled-Ref: Ops. And Maint. Manual		
TP A-1063	Turbo Prop Engine N <sub>2</sub> Ground Operation and Speed Restriction	12-18-80	2	12-01-81
TP 1064	Sundstrand Grease Part Number Change	08-18-80		
TP 1065	Heavy Maintenance Inspection Compliance-Optional Gas Producer Turbine Replacement	Cancelled		
TP 1066	Fuel/Control System Air Leak Safety Warning	09-15-80	2	11-22-10
TP 1067	Spectrographic Oil Analysis Program (SOAP) Versus Magnetic Drain Plug Lights - Safety Warning	09-30-80	3	11-01-96
TP 1068	Cancelled Prior to Publication			
TP 1069	Model 250 Series Engine Identification	Cancelled 04-07-08		
TP 1070	Model 250 Turbo Prop Fuel System Operational and Maintenance Guidelines	12-11-81		
TP 1071	Turbine "U" Ring Installation and Pressure Test	Cancelled-Ref: Ops. And Maint. Manual		
TP 1072	List of Model 250 Publications Indicating the Latest Revision as of March 30, 1982	Cancelled		
TP 1073	Cancelled Prior to Publication			

#### COMMERCIAL SERVICE LETTER INDEX

CSL No.	Title/Description	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1074	Cancelled Prior to Publication			
TP 1075	Inspection of No. 6 and 7 Bearing Pressure Oil Nozzle After Removal	Cancelled-Ref: Ops. And Maint. Manual		
TP 1076	250 Series II Plugs for Bleed Air Port of the Compressor Scroll	12-15-83	1	02-29-84
TP 1077	Cancelled Prior to Publication			
TP 1078	Cancelled Prior to Publication			
TP 1079	Cancelled Prior to Publication			
TP 1080	Cancelled Prior to Publication			
TP 1081	Benefits of an External Scavenge Oil Filter	08-1-84	2	07-28-05
TP 1082	TBO Extension Program, 250 Series Engines	09-14-84	3	04-30-96
TP 1083	Model 250 Rework Parts Policy	Cancelled		
TP 1084	Commercial Engine Bulletin Distribution	07-13-84		
TP 1085	Returning of CEB Compliance Sheets with 250 Engine Module to be Repaired	12-01-85	1	08-07-98
TP 1086	Commercial Engine Bulletin Classification	06-16-86	4	06-19-19
TP 1087	Cancelled Prior to Publication			
TP 1088	Model 250 Alignment Build Procedures	12-01-85	1	05-27-86
TP 1089	Guidelines for Operation of "On Condition" Modules	04-01-88		
TP 1090	Identification of Allison Power Parts (APP)	08-01-85	1	01-31-90
TP 1091	Cancelled Prior to Publication			
TP 1092	Field Vibration Test Procedure	10-17-86	10	06-19-19
TP 1093	Cancelled Prior to Publication			
TP 1094	Return Of Parts for Field Investigation at Allison Or Allison Authorized Maintenance Centers (AMC)	04-20-86	2	10-01-96
TP 1095	Contamination Removal (Water Rinse) Instructions Using Water Only	06-23-86	11	12-20-19
TP A-1096	Publications Authorization Procedures	11-03-86	5	11-01-96
TP 1097	Alert Document Compliance	01-31-87	3	10-01-96

CSL No.	Title/Description	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1098	Inspection of Model 250-B17 PTO Gear Splines on Engines Installed in Aircraft with Non-Beta Systems	07-31-87		
TP 1099	Longer Life Igniter Plugs	08-20-87	3	10-01-96
TP 1100	Chafe Wrapping Of Stainless Steel Tube Assemblies	05-01-88		
TP 1101	Warning Tags Attached to Fuel Oil, Air tubes, Fittings and Associated Components on 250 Series Engines	09-10-87	2	09-26-00
TP 1102	Cancelled Prior to Publication			
TP 1103	Model 250 Fuel System Operation and Maintenance Guide- lines	05-11-79	2	11-01-88
TP 1104	Cancelled Prior to Publication			
TP 1105	Serial Number Effectivity, Allison Commercial Engine Bulletin	05-01-88		
TP 1106	Commercial Engine Bulletin Incorporation Philosophy	04-30-88		
TP 1107	Installation of new Gas Producer Tiebolt Nut, P/N 23039751	Cancelled		
TP 1108	Rolls-Royce Customer Training	08-01-88	21	05-27-15
TP 1109	Series II Coated Compressor Wheels	08-01-88	1	04-01-89
TP 1110	Cancelled Prior to Publication			
TP 1111	Translation of Allison Technical Publications into Foreign Languages	11-01-88		
TP 1112	Use of Eastern European, United Kingdom, and Peoples Republic of China Specification Fuels in Rolls-Royce M250 Engines	04-01-89	7	03-26-14
TP A-1113	Use of Salvaged or Scrapped Parts in Allison Model 250/225 Engines	12-01-88	1	08-15-91
TP 1114	Cancelled Prior to Publication			
TP 1115	Cancelled Prior to Publication			
TP 1116	Seal Shelf Life (Age Control)	05-01-89	1	08-22-11
TP 1117	Operation Of Bendix Fuel Controls and Power Turbine Governors Exposed to Fire or Severe Overtemperature	04-14-89		
TP 1118	Cancelled Prior to Publication			
TP 1119	Purolator/Facet External Scavenge Oil Filter Inspection	02-01-90	3	05-03-10

#### COMMERCIAL SERVICE LETTER INDEX

CSL No.	Title/Description	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1120	Heavy Maintenance Inspection (HMI) Compliance Option (A)	02-28-90	7	06-21-16
TP A-1121	Maintenance Warning - External Lines	11-15-90	2	07-08-19
TP 1122	Model 250 Logbook Changes	11-15-94		
TP 1123	Model 250 Engine Designations and Applications	11-30-91	5	07-13-15
TP 1124	Compressor Case, Blade and Vane Erosion/Corrosion Inspection	02-28-91	5	05-20-13
TP 1125	"B" Nut Warning Placard	Cancelled		
TP 1127	Cancelled Prior To Publication			
TP 1128	Model 250 Turboprop Engine Mean Time Between Removal Recommendations on Use of Overhauled First-Stage Turbine Nozzles	04-30-93	1	05-31-94
TP 1129	Premature Engine Removals Due to Metal Generation From the 2 1/2 Bearing	04-30-93		
TP 1130	Max Flow Stop Adjustment F.C.U.	06-01-92		
TP 1131	Introduction of the "Long Sun Gear Shaft"	04-30-93		
TP 1132	Unapproved Hot Engine Cool Down Procedure	03-01-93	1	11-13-01
TP 1133	Recommendations in Conjunction with Engine Oil Change	04-30-93	1	04-15-98
TP 1134	Operation and Maintenance Manual/Publications Concerning Magnetic Chip Detector Guidelines	04-30-93		
TP 1135	Authorized Allison Repair/Overhaul/Facilities for the Allison Model 250 Engine	Cancelled-Ref Ops & Maint Manual		
TP 1137	Change in Commercial Engine Bulletin Index Format	06-15-93		
TP-A-1140	Inspection, Rework, and Overhaul of Parts Manufactured by Anyone Other Than Allison and/or Allison Approved Vendors and Suppliers	02-15-94	1	11-30-94
TP 1141	Engine, Accessory Gearbox Assembly - Part No. 6854424 Seal Installed on Power Turbine Overspeed Governor Pad	08-15-95		
TP 1142	Optimized Start Technique For Allison 250-B17 Series and 250-B17F Series Turboprop Engines	07-15-94		
TP 1143	Handling of Fluorocarbon Elastomer Preformed Packings and/or Seals	02-01-95		
TP 1144	Model 250 Power By The Hour®/Fleet Hour Agreement Program	09-30-94	6	Cancelled 02-22-08

#### COMMERCIAL SERVICE LETTER INDEX

CSL No.	Title/Description	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1145	Allison Model 250 Engine Customer Support and Service Parts Telephone Numbers	Cancelled 02-01-02		
TP 1146	Use of Rolls-Royce Military Surplus Parts in Commercial Engines	01-27-95	5 Reissue	04-23-02
TP 1147	Recommended Use of Airframe Accessory Filter for Remote Area Fueling	09-15-97		
TP 1149	Identification of a New Fuel Pump Vendor	11-01-95	1	06-30-97
TP 1150	Model 250 Publications Procurement Policy	02-15-96	3	03-03-08
TP 1151	Letterhead, Model 250 Commercial Engine Bulletins, Commercial Service Letters and Installation Bulletins	11-15-95		
TP 1152	Manufacturing Origin Request Procedure	02-20-96	3	07-23-04
TP 1154	Rolls-Royce Part or Assembly Modification	07-31-96	2	05-22-02
TP 1155	Potential for Model 250 Turboprop Engine External Static Oil Leakage	06-15-97		
TP 1156	No-Go Gages for Spline Inspection	11-15-97	Cancelled	02-10-14
TP 1158	Disposition of Old Engine and Module Data Plate	10-15-97	3	02-24-16
TP 1159	Return of Model 250 Field Parts for Investigation at Rolls-Royce	06-30-97	4	04-06-15
TP 1161	Commercial Engine Bulletin, CECO Fuel Pump Spline Inspection	09-02-97		
TP 1162	Use of High Thermal Stability (HTS) or Third Generation Oils	09-15-97	2	02-13-12
TP 1163	Hot Corrosion - Sulfidation	02-10-00	1	05-25-04
TP 1164	Inconel Bellows Incorporation in All 250 AlliedSignal (Bendix) Fuel Controls	02-27-98		
TP 1166	OEM Engine Warranty	04-15-99	1	07-08-16
TP A-1170	Model 250 Engine Cautions For Changes In Engine Noise	09-15-99		
TP 1171	Alternate Consumable Materials List	04-19-00	3	09-17-12
TP 1172	Rolls-Royce Model 250/Aviall Parts And Technical Publications Distribution	Cancelled 01-25-02		
TP 1173	Manufacturing Tooling Marks On Tubing Assemblies	04-11-00	1	04-27-09
TP 1174	Model 250 Lip Seals	09-07-00	3	05-16-14

#### COMMERCIAL SERVICE LETTER INDEX

CSL No.	Title/Description	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1175	Engine - New Publications Prices	08-01-00	1 Reissue	08-24-00
TP 1176	Special Pricing For 1st-stage Nozzle Shield	Cancelled 07-18-06		
TP-A-1177	Honeywell Extension Of Inconel Bellows	12-20-00		
TP 1178	Second Stage Nozzle Special Pricing Policy	Cancelled 03-15-10		
TP 1180	Black Oxide Removed From Specified Gears	04-05-01	1	04-08-03
TP 1181	Use of AN503-8-8 Screws In Honeywell Products	04-25-01		
TP 1182	Operations In Methane Laden Atmosphere	09-19-01		
TP 1183	Handling Instructions For Bare Metal Parts	09-19-01	1 Reissue	10-19-01
TP 1184	Shipment Of Fuel System Components	11-15-01		
TP 1185	Rolls-Royce Model 250 Engine Customer Support And Service Telephone Numbers	Cancelled 03-20-08		
TP 1186	MTU Manufactured Parts	01-08-02	1	02-02-17
TP 1187	Fuel System Contamination	04-23-02	2	07-20-09
TP 1188	Compressor Splined Adapter Wear	01-13-03	1 Reissue	01-22-03
TP 1189	Overhaul Manual MPI Requirements	01-13-03	1 Reissue	01-22-03
TP 1190	Gearbox Bore Alignment Check	05-02-03	1	08-27-04
TP 1191	Position Statement on Ude of Red Dye Contaminated Fuel	02-27-03		
TP 1192	Goodrich Pump and Engine Control Systems, Inc. (GPECS) AOG Hotline	08-26-04	1 Reissue	09-17-04
TP 1194	250 Engine Wash Procedures	05-27-04		
TP 1195	Cancellation Notice - Cancellation of AMC-OIL's and AMC-IL's	05-13-04		
TP 1196	Power Turbine Rotor Clamping	05-10-04		
TP 1197	Inspection for Engine Damage Following Failure of Non-Rolls-Royce Provided Engine Hardware	05-26-04	1	06-23-04
TP 1199	Model 250 E-Pubs Technical Publications	Cancelled 03-20-08		

CSL No.	Title/Description	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP-A-1200	Engine Flameouts Due to Snow or Ice Ingestion - Warning	09-15-80	3	10-06-05
TP 1202	Suspect Repairs	10-31-05		
TP 1203	Oil Filter Cap	10-12-07		
TP 1204	M250 Engine Warranty Guidelines	11-15-06	2	07-27-16
TP 1205	Maintenance of Turbine Oil Check Valve	02-07-07	1	09-07-09
TP 1206	Quick Disconnect Magnetic Plug Installation	02-07-07	1	11-17-15
TP 1207	Release of New Blisk Compressor Wheels	03-01-07		
TP 1209	Rolls-Royce Model 250 Fleet Hour Agreement Program	Cancelled 10-07-09		
TP 1212	Rolls-Royce use of Self Adhesive Labels on Certain Parts	06-30-08		
TP 1213	Rolls-Royce Model 250 Series II Engines Compressor Shafting Reminder	05-01-09		
TP 1214	TOTALCARE Comprehensive Maintenance Solution for the M250 Engine	10-07-09		
TP 1215	Jet A-1 Fuel System Icing Inhibitor (FSII) Notice	07-26-10		
TP 1216	Helicopter Wreckage in Brazil	08-06-12		
TP A-1217	No. 2 Bearing Installation Information	03-04-13	1	03-24-14
TP A-1218	Enhanced Awareness of Outer Combustion Cracks (OCC)	03-04-13		
TP 1219	Release of New Accessory Seals	03-24-14	4	01-05-16
TP 1220	New Directional PTO Seal Installation (For Single Lip Seal Engines Only	08-08-14		
TP 1222	Engine Control System- Identification Plate change	08-24-15		
TP 1223	Outer Combustion Case Leak TEC Inspection Video	10-19-16		
TP 1224	Release of B-Nut Tool (23083893) and Definition	10-24-16		
TP 1225	Electronic Availability of Commercial Service Letter	02-14-17	1	09-14-18
TP 1226	Engine Assembly- Parts Mutilation Manual	10-17-17		
TP 1227	First Stage Turbine Wheel Failure Followed By Inflight Power Loss Due to Over-Temperature Engine Operation	12-05-17		
TP A-1228	Enhanced Awareness of Loose or Broken Split Line Bolts/ Studs	02-09-18		

CSL No.	Title/Description	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
TP 1229	Engine Preservation and Storage	04-24-19		
TP 1231	Engine- Radiosotopes	11-07-19		
TP 1232	Oil Pressure Regulating Valve Adjustment	12-12-19		