



Rolls-Royce

**Rolls-Royce Corporation
T56-A-14LFE**

**COMMERCIAL ENGINE
BULLETIN
(CEB)**

**Technical Publications
Index**

November 1, 2023

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>Bulletin No.</u>	<u>Subject</u>	<u>Compliance</u>	<u>Published</u>	<u>Revised</u>
72- ENGINE				
72-4001	Cancelled Prior to Publication			
A-72-4002	Engine - Reduction Gear, Propeller Shaft Thrust Nut Cup Lock - Add	ALERT. At Next Overhaul or Repair	04-16-82	No. 1, 06-30-82
72-4003	Engine - Reduction Gear, Rear Housing Oil Seal - Add	At Next Overhaul	07-15-82	No. 1, 05-20-83
72-4004	Engine - Reduction Gear, Planet Gear Bearing Separator - Replace	Separators to be Installed in Complete Sets on a "Use Stock" Basis at Overhaul	12-08-77	No. 1, 07-31-79
72-4005	Engine - Combustion Liner Thermocouple Grommets - Replace	At User's Discretion at Next Overhaul or Repair	10-31-79	
72-4006	Cancelled Prior to Publication			
72-4007	Engine - Rear Carrier Bearing Inner Race Locking Keys - Replace	At Next Overhaul	02-20-81	No. 1, 09-30-81
72-4008	Engine - Accessory Drive Housing Union - Replace	At Next Overhaul, or When Oil Leakage is Present, Option of the Operator	08-31-80	No. 2, 01-00-89
72-4009	Engine - Reduction Gear, Main Drive Gear - Molybdenum Spray	At Next Overhaul at the Discretion of Overhaul Agent	05-01-81	No. 5, 07-15-92
72-4010	Cancelled Prior to Publication			
72-4011	Engine - Reduction Gearbox, Oil Pump Valve Shaft - Rework and Replace	At Next Overhaul	02-15-85	No. 1, 08-00-90
A-72-4012	Engine - Accessory Drive Housing - Inspect	Inspect Based on Flight Hours Listed in the CEB, and no Later than Next Overhaul	06-21-82	No. 2, 01-05-00
72-4013	Cancelled Prior to Publication			
72-4014	Cancelled Prior to Publication			
72-4015	Cancelled Prior to Publication			
72-4016	Engine - Combustion Liner Cross-over Tube Clamps - Add	At Next Overhaul	10-01-84	
72-4017	Engine - Turbine Assembly, Rear Bearing Support Cone Assembly, - Service Repair	"As Required" at Next Overhaul	3-13-85	No. 2, 9-15-98
72-4018	Cancelled Prior to Publication			
72-4019	Engine - Power Section Control Assembly, Diffuser Bleed Port Flange Cap - Replace	At Next Overhaul	03-16-84	
72-4020	Engine - Reduction Gear Assembly, Prop Shaft Thrust Nut Lock Cup Lock- Rework	At Next Overhaul or Repair	10-05-84	
72-4021	Engine - Spline-Turbine, Starter Shaft 3/4 Inch Drive	At Next Overhaul	03-20-86	
72-4022	Engine - Turbine Vibration Pickup Mount - Add	At Next Overhaul	07-14-86	No. 3, 08-23-99

June 1, 1993

Revised November 1, 2023

T56-A-14LFE INDEX

PAGE 1 OF 4

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>Bulletin No.</u>	<u>Subject</u>	<u>Compliance</u>	<u>Published</u>	<u>Revised</u>
<u>72- ENGINE (Continued)</u>				
72-4023	Cancelled Prior To Publication			
72-4024	Engine - Reduction Gear Tachometer Drive Idler Gear - Shot Peen	"As Required" at Next Overhaul	12-22-86	No. 3, 10-23-00
72-4025	Engine - Turbine 2nd-Stage Wheel - Inspect	When Compressor is Removed Removed for Premature Erosion Overhaul or Repair	01-00-89	No. 1, 03-30-91
72-4026	Engine - Reduction Gear Assembly Safety Coupling Intermediate - Inspect	Recommended at Next Overhaul	09-15-91	
72-4027	Engine - Air Inlet Housing, Inspect/Rework	Next Shop Visit or When Engine is Removed for Maintenance	03-15-92	No. 4, 03-16-18
72-4028	Engine - Reduction Gearbox Main Drive Gear, Serviceability Criteria	At Next Overhaul or Major Repair	09-30-92	No. 1, 02-12-01
72-4029	Engine - Reduction Gearbox Rear Carrier Bearing, Serviceability Criteria	Superseded by CEB 72-4035	12-21-92	No. 1, 12-10-02
72-4030	Engine - 15 Micron Pressure Oil Filter, Installation	Replace on Attrition Basis	03-31-95	
72-4031	Engine - 5th-Stage Compressor Blades Inspection Requirement	Recommended at Intermediate and Overhaul Maintenance Activities	09-30-93	
72-4032	Engine - Reduction Gear Assembly - Enhanced Reliability Reduction Gearbox	"As Required" at Next Overhaul	02-28-94	No. 8, 10-13-05
72-4033	Planet Gear and Bearing Assembly Replaceable Roller Sets	Recommended at Intermediate and Overhaul Maintenance Activities	05-23-96	No. 1, 07-08-03
72-4034	RGB - Planet Journal Plugs	Recommended at Next Shop Visit	08-16-01	
72-4035	Rear Carrier Bearing (P/N 6871650) Inspection	Recommended at Next Overhaul or Major Repair	01-26-98	No. 1, 12-10-02
72-4036	Approved Liquid Gas Path Cleaners - Motoring Wash	Comply at Earliest Opportunity	02-01-98	No. 2, 08-25-14
72-4037	Compressor Inlet Blockage	Recommended at Intermediate and Overhaul Maintenance Activities	02-01-98	
72-4038	Oil Foaming	Recommended at Organizational, Intermediate and Overhaul Maintenance Activities	02-01-98	No. 1, 04-06-18
72-4039	Compressor Air Inlet Housing Inspection / Rework	CANCELLED, Superseded by CEB 72-4027		
72-4040	Rub Tolerant Turbine Vanes and Spacers/IN-718 Material Vane Case	Recommended at Next Shop Visit	05-17-99	No. 5, 10-30-23
72-4041	Rear Compressor Bearing P/N 23057662	Recommended at Next Shop Visit	05-14-99	No. 1, 05-05-00
72-4042	Torquemeter Mid-Bearing PN 23064888	Recommended at Next Shop Visit	05-14-99	No. 2, 03-14-11

June 1, 1993

Revised November 1, 2023

T56-A-14LFE INDEX

PAGE 2 OF 4

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>Bulletin No.</u>	<u>Subject</u>	<u>Compliance</u>	<u>Published</u>	<u>Revised</u>
72- ENGINE (Continued)				
72-4043	14th Stage Compressor Wheel Silver/Indium Plating Replacement	Recommended at Next Shop Visit	08-10-99	No. 2, 07-20-00
72-4044	New Prop Shaft Seal Kit (P/N 23053159)	Recommended At Next Shop Visit	09-11-00	
72-4045	RGB Carrier Bearing Cage Bolt Hole Addition of Chamfer	Recommended At Next Shop Visit	08-23-00	
72-4046	Reduction Gearbox - Nose Bearing Cage - Replacement	Recommended At Next Shop Visit	07-30-01	
72-4047	Improved Igniter and Combustion Liner Supports and Seals	Recommended when engine is disassembled	12-15-04	
72-4048	Release of Improved 1st-Stage Turbine Blade	Customer Option	03-18-02	No. 1, 10-22-07
A-72-4049	Engine - 1-2 Stage Turbine Spacer, Inspection for Proper Heat Treating	Recommended Before Cycle Limit	02-15-02	No. 3, 08-06-15
72-4050	Series III Turbine 1st-Stage Vane, Improved Durability Part Number 23031780, 23031781, 23031782, and 23031783	Customer Option	05-28-04	
72-4051	Engine, 1st, 2nd, 3rd, 4th-Stage Turbine Wheel - Hardness Inspection	Recommended Before Cycle Limit	01-23-04	
72-4052	Engine - Reduction Gearbox, Main Power Train Gears Inspection and Serviceability	Recommended at Next Overhaul	04-26-05	No. 2, 03-03-06
72-4053	New 5th & 10th Stage Bleed Gaskets P/N's 23079417 & 23079416	Recommended Incorporation by Attrition	10-31-05	No. 1, 10-09-06
72-4054	Reduction Gearbox (RGB) Carrier Oil Delivery Flange & Sun Gear Lube Tube Assembly Rework	Recommended at Next Shop Visit	05-12-08	
72-4056	Replacement of Narrow Rim 1st to 2nd-Stage Assemblies P/N's 6844632 and 23033463	Recommended at Next Shop Visit	02-26-07	
72-4057	Custom 450 1st-stage Compressor Vane Assembly, P/N 6878361	Optional	05-12-08	
72-4058	Reduction Gearbox Assy - Pinion Shaftgear Inspection	Recommended at Next Shop Visit	04-30-10	
A-72-4059	Turbine Assembly - Turbine Wheel Inspection	Recommended	05-06-10	No. 2, 02-16-17
72-4060	15 Micron Pressure Oil Filter - Impending Bypass Indicator Replacement	Optional	03-14-11	
72-4061	Turbine Assembly - Turbine Inspection Spacer Inspection	Recommended	11-10-15	No. 2, 04-04-17
72-4063	Reduction Gearbox Assembly- Two-Piece Starter Drive Shaft Seal		01-29-16	
72-4065	T56-A-14 to T56-A-14 Series 3.5 Engine Conversion	Optional	12-06-13	

June 1, 1993

Revised November 1, 2023

T56-A-14LFE INDEX

PAGE 3 OF 4

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>Bulletin No.</u>	<u>Subject</u>	<u>Compliance</u>	<u>Published</u>	<u>Revised</u>
<u>72- ENGINE (Continued)</u>				
72-4067	Engine - Suspect External Scavenge Oil Pump Assembly P/N 6846567 Inspection for End Face Clearance of Internal Gears	Recommended	04-09-14	No. 2, 09-23-19
72-4072	Engine - Torquemeter Housing Splitline Self-locking Nuts, P/N 6749294-524 Replaced by P/N's AS3477-11 or AS20626	Recommended	03-22-23	
72-4073	Engine-Health and Safety Caution Regarding Hexavalent Chromium Deposits found on Gas Turbine Components	Optional	11-16-20	
72-4075	Propeller Shaft Planet Gear Bearing Bore Index Marking	Recommended	10-01-21	
72-4076	Disposition Guidance for Turbine Spacers with Visually Prominent Burrs Near the Anti-Rotation Pins		02-23-23	

73- ENGINE FUEL AND CONTROL

73-4001	Engine Fuel and Control - Fuel Control Thermostat Capillary Tube - Replace	To be Accomplished on a "Use Stock" Basis	11-13-79	
73-4002	Engine Fuel and Control - Electronic Temp Datum Control, Amplifier Chopper - Replace	To be Accomplished on a "Use Stock" Basis	10-24-79	
A-73-4003	Engine Fuel and Control - Fuel Control Bendix Model AP-B3-Inspect For Presence of 119024 Cotter Pins In Weight Pivot Pins	Prior to Customer Delivery or 25 Flight Hours, or Prior to Flight. Refer to CEB	03-22-82	
73-4004	Cancelled Prior to Publication			
73-4005	Engine Fuel and Control - Anti-Icing Air Tube Probe - Replace	At Next Overhaul	03-05-86	No. 1, 09-01-90
73-4006	Engine Fuel and Control - TSS Carbon Switch Assembly	At Next Overhaul	09-30-86	No. 2, 06-00-88
73-4007	Engine Fuel and Control - Shrouded Anti-Ice Probe - Rework	To be Accomplished Concurrently With CEB 73-4005	07-00-88	No. 2, 03-31-08
73-4008	Cancelled Prior to Publication			
73-4009	Cancelled Prior to Publication			
73-4010	Turbine Engine Main Fuel Control New Service Limits for Governor Shafts	Recommended at Next Overhaul or Repair	09-01-90	No. 2, 05-19-98
73-4011	Fuel Nozzle Upgrade Instructions	At Next Overhaul	09-25-06	No. 2, 10-27-14

74-IGNITION

74-4001	Electrical System - Ignition Exciter Solid State Chopper and Rectifier - Add	At Next Exciter Overhaul	09-28-79	No. 1, 09-15-80
74-4002	Ignition - New Solid State Ignition Relay P/N 23090200	Optional	08-22-14	

June 1, 1993

Revised November 1, 2023

T56-A-14LFE INDEX

PAGE 4 OF 4