



Rolls-Royce

**Rolls-Royce Corporation
T56-A-14LFE**

**COMMERCIAL
OVERHAUL
INFORMATION LETTERS
(COIL)**

**Technical Publications
Index**

August 8. 2019

Rolls-Royce

COMMERCIAL OVERHAUL INFORMATION LETTER INDEX

<u>COIL No.</u>	<u>Subject</u>	<u>Published</u>	<u>Revised</u>
4001	Reduction Gearbox Negative Torque Signal (NTS) Plunger Bore Repair	04-25-80	
4002	Shot Peening of 1st-Stage Compressor Wheels, 6841211, 6871371, 6829661, 6844081, 6850701, 6805651, and 6789681	12-21-84	No. 6, 07-01-14
4003	Pinion Shaftgear Assembly MPI Inspection	03-00-89	
4004	Critical Shafting Inspection for Grinding Burns	02-28-91	
4005	Coordinator Control - Assembly Grease Change	02-28-91	
4006	3rd-Stage Turbine Wheel Inspection 6845593 (Series III)	01-30-93	
4007	Planet Gear and Bearing Assembly, Replaceable Roller Sets	11-30-93	No. 1, 07-08-03
4008	Turbine Coupling Shaft, Balance Procedures (Data Incorporated In 14LFE Manuals)	Cancelled	
4009	Non-AEP Coating 2nd-Stage Blade, 6898062	08-31-95	
4010	Wide Rim, 1st to 2nd Stage Turbine Spacer Rework and Turbine Clamp Bolt Torque Change	10-31-96	No. 2, 01-15-02
4011	Fuel Control Speed Piston O-Ring Seal	12-08-97	No. 2, 06-01-01
4012	Series III 1st Stage Turbine Saddle Vane - Broken Tang	02-01-98	
4013	Metco 445NS Replacement for Sprabronze AA	12-08-97	No. 3, 07-11-03
4014	Second and Third Stage Turbine Vane Honeycomb Replacement	03-01-99	No. 2, 11-15-06
4015	Rear Carrier Cage Bolt Torque	12-15-98	
4016	Reduction Gear Housing Starter Drive Shaft Magnetic Oil Seal , Removal, Disassembly Cleaning, Inspection, Assembly and Installation.	03-15-99	No. 1, 09-15-03
4017	Torquemeter Housing Plate Change From Cadmium To Nickel.	02-10-99	
4018	Rear Turbine Bearing Support Weld Wire and Annealing Process	09-13-99	
4019	Replacement for Brayco 814 Oil	04-05-00	
4020	14th - Stage Compressor Wheel - Alternative Repair Method for Hub OD/ID - Rework	01-08-04	
4021	Inner Rear Exhaust Cone-Anti-Rotation Slot Inspection/Repair	12-12-00	
4022	Improved Bearing Designs Released to T56/501D Series I, II, III Engine Models	05-18-01	No. 1, 10-19-05
4023	Compressor Case Silicone Resin Removal-Rework	12-15-00	
4024	Anti-Ice Solenoid Valve, P/N 23052049	01-17-01	
4025	Cancelled Prior to Publication		
4027	Fuel Nozzle Overhaul Procedures	12-12-01	No. 1, 01-10-02
4028	Compressor Blade Surface Finish, Stages 10-14	01-29-02	
4029	Metco 444, Alternate Method to Metcoloy 2 (Metco 2)	07-22-03	
4030	Compressor Wheel Plating - Hydrogen Embrittlement Relief	01-23-03	Reissue 02-04-04
4031	Propeller Thrust Nut, HVOF Tungsten Carbide Coated Sealing Surface	10-07-04	
4032	Approval of Alternate Materials for BUNA-N Rubber on the Air Inlet Housing Struts	10-06-04	

Rolls-Royce

COMMERCIAL OVERHAUL INFORMATION LETTER INDEX

<u>COIL No.</u>	<u>Subject</u>	<u>Published</u>	<u>Revised</u>
4033	Approval of Metco 73NS-2 or Metco 72F Plasma Spray as Alternate Repairs for: Vane and Seal Support Internal Diameter (6870406) Inner Combustion Casing Piston Ring Grooves (6789860)	10-07-04	
4034	Cast Turbine Front Bearing Support Repair P/N 23071468	01-18-05	No. 3, 09-22-16
4035	Compressor Tie Bolt Plating	03-02-05	
4037	P/N 23009372 Turbine Vane Case - Add Chamfer to Inner Vane Slots	04-21-08	
4038	Compressor Case Blade Track: Application of XPT 268 and Alternates Coatings	10-06-08	No. 1, 01-29-19
4039	Inspection of Oil Jet Nozzle, PN 23055584, At Reduction Gearbox Depot Visit	03-17-17	