



Rolls-Royce

**Rolls-Royce Corporation
M250-B17F**

**COMMERCIAL ENGINE
BULLETIN
(CEB)**

**Technical Publications
Index**

March 3, 2020

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 72-2001	Engine, Turbine Assembly, Fourth-Stage Nozzle Diaphragm Locating Key Welds -Modify	10-16-89	2	11-15-96		
TP 72-2002	Cancelled Prior to Publication					
TP 72-2003	Engine, Compressor Assembly, Addition of Body-Bound Bolts to Compressor Case Half Splitline	05-01-89			07-31-90	
TP 72-2004	Engine, Compressor Assembly, Front Support - Modify	06-01-89	2	12-03-12		
TP 72-2005	Engine, Turbine Assembly, Second Stage Turbine Wheel, Reduced Diameter Balance Piston Seal Knife	04-01-89				
TP 72-2006	Engine, Engine Assembly Shipping Container - Modify	11-01-88	2	04-15-93		
TP 72-2007	Engine, Gearbox Assembly, Installation of New 3 and 4 Roller Bearings	09-30-90	3	10-31-96		
TP 72-2008	Cancelled Prior To Publication					
TP 72-2009	Engine, Accessory Gearbox Assembly, Centrifugal Breather Gear - Improved Configuration	01-31-89	1	06-15-94		
TP 72-2010	Cancelled Prior to Publication					
TP 72-2011	Engine, Turbine Assembly, Gas Producer Support, Addition of Brazed or Welded Wear Pads	05-01-89	3	06-15-93		
TP 72-2012	Engine, Gearbox Assembly, Starter Generator Gearshaft, Modify Spline No-Go Gage	06-01-89				
TP 72-2013	Cancelled Prior To Publication					
TP 72-2014	Engine, Gearbox Assembly, Spur Adapter Gearshaft, Modify 2 1/2 Bearing Guide	03-01-89	1	08-01-89		
TP 72-2015	Engine, Accessory Gearbox Oil Filter Housing, Add Bronze Bushing to the "Oil Out" Port	07-01-89	2	10-20-17		
TP 72-2016	Engine, Turbine Assembly, New Gas Producer Turbine Tiebolt Spanner Nut	Cancelled				
TP 72-2017	Engine, Accessory Gearbox, Install New Pressure Oil Tube	Cancelled				
TP 72-2018	Cancelled Prior to Publication					

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 72-2019	Engine-Propeller Reduction Gearbox, Rear Housing Rework to Maintain Interchangeability	03-15-91	1	07-30-93		
TP 72-2020	Engine, Tooling, Power and Accessories Gearbox Bearing Removal Puller Kit, Modify	06-01-89				
TP 72-2022	Shipping Container Rework, PC Air Filter Clearance	10-01-91				
TP A-72-2023	Engine, Turbine Assy., Alseal Coating of Power Turbine Inner and Outer Shafts	02-28-90	7	02-29-96	08-31-95	
TP 72-2024	Engine, Compressor, Front Bearing Housing Assembly - Modify Housing Assembly	07-25-90	1	06-30-93		
TP 72-2025	Engine, Accessory Gearbox, Install New Pressure Oil Tube	04-30-90	1	06-21-91	12-31-90	
TP 72-2027	Engine, Combustion Liner, Rework	Cancelled				
TP 72-2029	Engine, Turbine Assembly, First-Stage Nozzle, Modify	04-01-89	1	11-15-90		
TP A-72-2030	Engine, Turbine Assembly, Turbine Spline Adapter P/N , 6898784 Replace Certain Suspect Adapters	04-30-90	1	07-15-91		
TP 72-2031	Cancelled Prior To Publication					
TP A-72-2032	Engine, Turbine Assembly, Multi-Engine Exhaust Collector Horizontal Support Repetitive Inspection and Modification	02-28-92	2	05-31-94		
TP 72-2033	Engine, Turbine Assembly, Authorization to Reidentify Semi-finished 2nd Stage Nozzles	12-31-93	7	03-29-18		
TP 72-2034	Engine Compressor Assembly, Improved Compressor Shroud Coating	10-15-91	1	11-15-93		
TP 72-2035	Engine, Compressor Assembly, Addition of Puller Groove for Removal of No. 2 Bearing	07-31-92	1	12-15-94		
TP 72-2037	Engine, Gearbox Assembly, Turbine Pressure Oil Fitting, Add Seal	12-15-92	1	01-26-01		
TP 72-2038	Engine, Turbine Assembly, Combustion Liner Rework	09-01-91	2	06-18-98		
TP 72-2039	Engine, Turbine Assembly, -C20R & -B17F Series Multi-Engine Configuration Conversion for use on -C20R & -B17F Series Single Engine Applications	08-31-91	2	01-19-09		

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 72-2041	Inspection of Oil Filter Inlet Tube Assembly, P/N 6876925A for Proper Engagement	11-15-91				
TP 72-2042	Engine, Power and Accessory Gearbox Housing Assembly, Rework to Remove Web Wall Material from Casting Housing	01-25-93				
TP 72-2044	Model 250 Engine or Module Conversion Authorization	09-30-85	12	03-06-19		
TP A-72-2046	Engine, Fuel, Lube and Air Assembly, Fuel Hose Assembly 23005205, Replace	07-30-92				
TP 72-2047	Engine, Gearbox Assembly, Release of New Bracket to Eliminate Interference with Gearbox - Replace	06-30-93				
TP 72-2048	Engine, Turbine Assembly, Release of New Horizontal Fireshield and Access Panel - Rework	07-30-93				
TP 72-2049	Engine, Turbine Assembly, Release of New No. 8 Bearing and Retaining Plate	05-31-94				
TP 72-2050	Engine Compressor Assembly, Impeller, Reidentify Certain Impellers for Increased Life Limits	06-01-89	1	04-15-93		
TP A-72-2051	Engine Assembly, Fireshield Retaining Nut Torque	10-30-93				
TP 72-2052	Customer Option Engine "Quick Disconnect" Drain Plugs , Install	01-31-79	9	11-07-19		
TP 72-2053	Engine, Compressor Assembly, Revised Clamping of No. 1 Bearing Oil Tube to Eliminate Interference	10-31-94				
TP A-72-2054	Engine, Accessory Gearbox Assembly Removal of P.T. Overspeed Governor and Inspection for Presence of Part No. 6854424 Seal	08-15-95				
TP A-72-2055	Engine, Quick Disconnect Magnetic Plugs - Inspect Locking Pins and Insert Slots for Wear	Cancelled				
TP A-72-2057	Engine, Gearbox, Removal of Certain Pinion Gears	10-04-95	1	11-30-95		
TP A-72-2058	Engine, Turbine, Inspection of First Stage Nozzle Shield Dome Detail for HMI or Overhaul	01-15-96	2	05-12-99		

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 72-2061	Engine, Compressor Assembly, Compressor Rear Support, No. 2 Bearing Bore and Thrust Face, Addition of Wear Resistant Coating	04-30-98				
TP A-72-2063	Engine, Gearbox Assembly - Oil Delivery Tube - Replace	03-15-99	2	02-02-04		
TP 72-2065	Engine, Turbine Assembly - Recoating Of Power Turbine Inner Shaft	11-22-99	2	02-22-10		
TP 72-2066	Engine, Gearbox Assembly - Release Of New Helical Torquemeter Gearshaft Assemblies and Internal Retaining Rings (Damper)	11-05-99	3	05-03-10		
TP A-72-2069	Engine, Turbine - Inspection Of 1st-Stage Nozzle Shield Dome	03-29-00	9	04-30-18		
TP A-72-2070	Engine, Turbine Assembly - Gas Producer Rotor Assembly - Replace Turbine Tie Bolt	05-09-00	2	11-03-08		
TP A-72-2071	Engine, Gearbox - Inspection For Installation Of Torquemeter Retaining (Damper) Ring	02-15-00				
TP 72-2072	Engine - Compressor with Improved Airflow Characteristics	06-08-00	2	10-12-15		
TP A-72-2073	Engine, Compressor Assembly - Visual Inspection Compressor Scroll Pressure Probe Elbow (Pressure Probe)	05-05-00	1	08-02-00		
TP A-72-2074	Engine, Turbine - Replacement Of 2nd-Stage Nozzle Diaphragm	10-24-00	4	11-22-19		
TP A-72-2083	Engine, Gearbox Assembly - Inspection of Helical Torquemeter Gearshaft Assembly	10-03-01	2	07-28-17		
TP 72-2084	Engine, Main Accessory Gearbox - Release of Rework And Reidentified Lip Seals	04-25-02				
TP 72-2085	Engine, Compressor Assembly - Release of New No. 1 Bearing (23066679)	08-16-04	6	01-25-16		
TP 72-2086	Engine, Gearbox Assembly - Replacement of Breather Gear Seal	02-07-05				
TP A-72-2089	Engine, Turbine Assembly - Power Turbine Outer Shaft	10-09-06	3	01-19-09		
TP 72-2090	Engine, Turbine - Inspection of Sump Assembly, Oil - Gasifier Turbine Bearing Support	02-19-07	1	07-12-07		
TP A-72-2091	Engine, Turbine Assembly - Steady-State Operation Avoidance Limit	12-22-06	7	01-10-19		

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 72-2092	Engine, Fuel and Control - Removal of the PY Line and PT Governor Cable	04-15-95	4	05-29-09		
TP 72-2093	Engine - Power Turbine with Improved Airflow Characteristics	06-08-00	4	04-21-17		
TP 72-2096	Engine, Turbine Assembly - Replacement of Turbine Gas Producer Forward Labyrinth Seal	09-13-10	1	08-15-11		
TP 72-2098	Engine, Compressor Assembly - Inspection & Replacement of Metco 52C Coated Cases	11-29-10	1	12-05-11		
TP 72-2099	Engine - N2 Shafting Replacement	04-14-14	1	06-16-14		
TP A-72-2101	Engine, Compressor Assembly - Inspection of Front Support P/N M250-10051, M250-10052, M250-10059, M250-10060	07-29-14	1	08-22-14		
TP 72-2102	Engine - No. 5 Bearing Retaining Ring Replacement	09-03-14	1	07-13-15		
TP 72-2103	Engine Turbine Assembly- Inspection of 3rd-Stage Turbine Wheel Slotted Shroud	04-06-15	1	05-20-15		
TP 72-2104	Engine - No. 8 Bearing Manufactured by NHBB	03-27-15				
TP 72-2107	M250 Gearbox Oil Check Valve, Guide, Poppet, Check Valve Replace P/N 23085911 and 6898840 with New P/N M250-10893 or P/N M250-10894	10-16-19	1	01-08-20		
TP 72-2108	Engine, Turbine, 2nd-Stage Turbine Wheel Replacement	09-07-18	1	10-09-18		

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 73-2001	Engine, Fuel and Control, Allied /Bendix Fuel Control Models DP-N2 and DP-P2 - Increase Minimum Flow Setting	01-31-89				
TP 73-2002	Cancelled Prior to Publication					
TP 73-2004	Engine, Fuel and Control, Fuel Control Damped Metering Valve With Increased Clearance	03-31-90	1	03-29-91		
TP 73-2006	Cancelled Prior to Publication					
TP 73-2007	Engine, Fuel and Control, Elimination of Interference, Fuel Cutoff Rod and 200 Amp Starter Generator	09-30-93 Cancelled 09-07-09	1	02-28-94		
TP 73-2008	Cancelled Prior to Publication					
TP A-73-2011	Engine Fuel and Control, Disarm N ₂ (Electronic) Overspeed Control System-Multi Engine Aircraft	03-15-92	2	11-15-93	01-01-94	
TP A-73-2012	Bendix Main Fuel Controls Used on Model 250 Series Engines - Application of NYE Synthetic Oil 608 to Beryllium Copper PC Bellows Assembly	Cancelled				
TP 73-2013	Engine, Fuel and Control, Release of New Fuel Control With Stronger Bypass Valve Cover Retaining Screws, Modify	02-15-93	1	12-07-93		
TP A-73-2014	Engine, Fuel and Control, Fuel Control Bellows, Replace	11-18-93	4	10-09-01		
TP A-73-2015	Engine, Control System, Coordinator Power Input Lever	10-15-93	2	11-01-93		
TP 73-2016	Engine, Fuel and Control - Rework of Fuel Control Throttle Shaft to Add Lubrication Channel to Lubricate the Throttle Shaft	08-30-94	1	10-31-97		
TP 73-2018	Engine, Fuel and Control, Release of New Design Shaft Seal For CECO Model MFP 263 and 264 Fuel Pump	07-31-96				
TP 73-2019	Engine, Fuel and Control, Coordinator Support Bracket Attach Bolts, Replace	06-17-96	1	03-10-98		
TP 73-2020	Engine, Fuel and Control - Fuel Control Drive Bearings - Replace	04-10-97	4	05-17-10		
TP 73-2021	Engine, Fuel and Control System - Coordinator Control Assembly - Installation of Longer Bolt	10-31-97				

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 73-2022	Engine, Fuel and Control - Removal of N2 Overspeed System From 250-C20R Series Engines And B17F/1 Series Engines in Multi-Engine Installations	03-10-99	1	06-16-08		
TP 73-2023	Engine, Fuel and Control, Fuel Control Stop Nut - Rework	08-31-97	2	10-13-99		
TP A-73-2024	Engine, Fuel and Control - CECO Engine Driven Fuel Pump - Internal Spline Inspection	08-21-97				
TP 73-2025	Engine, Fuel and Control - CECO MFP-263 Fuel Pump - Replace	04-30-98				
TP 73-2026	Engine, Fuel and Control - AlliedSignal (Bendix) Main Fuel Control - Incorporate One Piece Bypass Valve Sleeve	01-08-99	1	09-28-99		
TP A-73-2027	Engine, Fuel and Control - Honeywell Fuel Control Unit and Power Turbine Governor - Internal Spring Replacement	10-05-98	3	08-13-04		
TP 73-2028	Engine, Fuel and Control - Release of New Bypass Retention Plate	04-20-01	1	11-15-02		
TP 73-2030	Engine, Fuel and Control - Honeywell (Bendix/AlliedSignal) Main Fuel Control Unit - One Time Inspection of Screws	04-06-01	1	05-13-02		
TP 73-2031	Engine, Fuel and Control - Goodrich Engine Driven Fuel Pump Improved Drive Shaft Durability	04-07-04	3	03-06-19		
TP A-73-2032	Engine, Fuel Control - Release of New Fuel Nozzle	09-04-03	1	08-30-04		
TP 73-2033	Engine - Fuel & Control - Fuel Control Cutoff Lever	12-21-07 Cancelled 09-07-09				
TP 73-2034	Engine, Fuel and Control - Honeywell Main Fuel Controls - Replacement of Cut-off Valve Lever and Shaft Assembly, and Drive Body Assembly	10-07-09	2	02-18-16		
TP 73-2035	Engine, Fuel and Control - Honeywell Main Fuel Controls - Verification of Fuel Flow Calibration	05-18-09				
TP 73-2037	Engine - Fuel Nozzle Spray Tip/Inner Air Shroud Replacement	09-09-13	1	01-13-14		
TP 73-2038	Engine, Fuel & Control - Honeywell Main Fuel Controls - Replacement of the Bypass Valve Sleeve	04-09-12	2	12-01-15		

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 73-2039	Engine - Fuel and Control - TECS Engine Driven Fuel Pump Internal Spline Inspection	12-09-14	1	01-14-15		
TP 73-2040	Engine, Fuel and Control- Fuel Control New Drive Bearings	10-26-17				
TP 73-2041	Engine, Fuel and Control- Honeywell Main Fuel Controls- Verification of Minimum Fuel Flow Setting	07-20-18	1	10-12-18		

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 74-2001	Engine, Electrical - Start Counter Assembly - Removal/Installation	01-15-99	1	03-17-99		
TP 74-2002	Engine, Ignition System- Repair or Re- placement of Select Rolls-Royce P/N 6899093 (Unison P/N 10-614950-1) Igni- tion Exciters	06-23-17				

M250-B17F INDEX

Rolls-Royce

COMMERCIAL ENGINE BULLETIN INDEX

<u>CEB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>	<u>Compliance Requirement</u>	<u>Compliance Completed</u>
TP 75-2001	Engine, Compressor Bleed Valve, Introduction of New Bleed Valve Assembly	03-15-92				
TP 75-2002	Engine, Compressor Bleed Valve, Re- duced Diameter Vent Hole	07-30-89				
TP 75-2003	Engine, Air System, Bleed Valve, Improved Valve Stem Bushing - Install	10-15-90	2	04-15-93		
TP 75-2004	Engine, Compressor Bleed Valve, Release of New Bleed Valve Which Incorporates Refined Calibration Limits	01-10-97	1	06-15-98		
TP 75-2005	Engine - Bleed Valve Modification For Use With Increased Airflow Characteristics Compressor	06-08-00				

M250-B17F INDEX

Rolls-Royce

INSTALLATION BULLETIN INDEX

<u>IB No.</u>	<u>Subject</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
TP 2001	Engine Assembly, Installation of Inverted Flight Valve on 250-B17D or 250-B17F Engines	06-01-89		
TP 2002	Removal of External Sump Tank from B17F/1 Engines for Non-Beta Installations	03-29-91	1	10-31-94
TP 2003	Tailoring of Engine & Systems for use in Schweizer Aircraft Corporation RU-38B Aircraft	09-22-08	1	08-13-12
TP 2005	Installation of No. 1 Bearing Sump Tank	12-05-11		06-27-15
TP 2007	Engine, Propeller Reduction Gearbox, Beta Control/Coordinator Kit	01-21-13		

M250-B17F INDEX