

# Rolls-Royce Corporation M250-C30

# COMMERCIAL ENGINE BULLETIN (CEB)

# Technical Publications Index

March 3, 2020

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3001	Engine, Compressor No. 1 Bearing Support Indexing - Add	06-19-79				
72-3002	Gearbox, Oil Valve Check - Replace	06-22-79				
A-72-3003	Engine, Power and Accessory - Gearbox Generator and 77 Tooth Spur Idler Gear- shafts - Replace	05-18-79	2	09-01-94		
72-3004	Engine, Compressor No. 1 - Bearing Oil Pressure Reducer - Replace	05-01-79	1	08-15-79		
72-3005	Engine, Compressor Mount Assembly -Replace	11-30-81	3	01-30-83		
72-3006	Engine, Power and Accessory Gearbox Cover Assembly Fuel Pump Drive Seal Bore Chamfer - Add	06-11-79				
72-3007	Product Improvement - Engine, Anti-Icing Solenoid Valve - Reposition	12-05-78				
72-3008	Gearbox, Cage No. 2 1/2 Bearing - Modify	03-21-79				
72-3009	Engine, Spur Adapter Gearshaft-To-Compressor Rotor Spline Piston Ring - Replace	03-20-79				
72-3010	Engine, Outer Combustion Case - Rework	Cancelled				
72-3011	Cancelled Prior to Publication					
72-3012	Engine, Power and Accessory Gearbox - Pinion Bearing Oil Nozzle - Rework	12-15-79	1	03-15-80		
72-3013	Gearbox, Power - Accessory Oil Delivery Tube - Replace	10-14-79	4	12-04-95		
72-3014	Engine, No. 1 Bearing Oil Pressure Supply Tube Clamp - Add	04-30-79	1	12-07-79	11-30-79	
72-3015	Cancelled Prior to Publication					
72-3016	Engine, Gearbox Housing & Cover Assembly Oil Pressure Ports Helical Coil Inserts - Add	02-15-80	1	03-15-81		
72-3017	Engine, Power & Accessory Gearbox Cover Assembly Turbine Support Studs - Replace	07-30-80	4	01-14-10		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3018	Engine, Compressor Discharge - Air Tube Flange Doubler Plates - Add	03-10-80	1	07-15-80		
72-3019	Engine, Turbine First-Stage Nozzle Assembly - Replace	Cancelled- REF: CEB 72-3031				
72-3020	Engine, Power & Accessory Gearbox Spur Adapter Gearshaft No. 2-1/2 Bearing Journal - Rework	08-15-80	1	04-30-81		
72-3021	Cancelled Prior to Publication					
72-3022	Engine, Power & Accessory Gearbox Oil Delivery Tube - Replace	07-15-80	2	10-30-80		
72-3023	Engine, Turbine Assembly - Exhaust Collector Retaining Rings - Add	12-15-79	2	09-15-90		
72-3024	Engine, Turbine Assy - Horizontal Fireshield - Modify	05-15-80				
72-3025	Engine, Power Turbine - Outer Coupling Nut - Rework	10-15-79	3	04-30-85		
72-3026	Engine, Start Counter Mounting Bracket Edge Radius - Modify	05-15-80				
72-3027	Engine, Fireshield- Insulation Blanket -Rework	03-28-80	1	02-28-81		
72-3028	Engine, Magnetic Plugs - Replacement	Cancelled- REF: CEB 72-3060				
72-3029	Engine, Power & Accessory Gearbox PTO Gearshaft Grooves - Add	Superceded by CEB 72-2184 and 72-3226				
72-3030	Engine, Compressor Scroll Bleed Passage - Plug	02-07-80				
72-3031	Engine, Turbine First-Stage Nozzle Assembly - Modify	06-15-80	4	08-30-82		
72-3032	Engine, Turbine Assembly - No. 6 & 7 Bearing Pressure Oil Nozzle Assembly - Replace	04-15-80	2	02-28-81		
72-3033	Engine, Gearbox Housing and Cover Assemblies Scavenge Oil Ports Helical Coil Inserts - Add	10-30-80	2	04-29-16		
72-3034	Engine, Power & Accessory Gearbox No. 2-1/2 Bearing Cage Scallops - Add	07-15-80	2	10-30-80		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3035	Engine, Magnetic Plugs - Replace	Cancelled- REF: CEB 72-3060				
A-72-3036	Engine, Turbine Second-Stage Nozzle - Modify	08-15-80	4	05-01-89	11-30-89	
72-3037	Cancelled Prior to Publication					
72-3038	Engine, Turbine Second-Stage Wheel - Modify	08-15-80	1	10-30-80		
72-3039	Engine, Power & Accessory Gearbox Pinion Gear Bearing - Replace	08-30-80	1	02-28-81		
72-3040	Engine, Turbine Exhaust Collector Flow- splitter - Modify	11-30-80	3	05-01-84		
72-3041	Cancelled Prior to Publication					
72-3042	Engine, Compressor Impeller Rear Stub Shaft - Repair by Modification	09-30-80	3	11-15-83		
72-3043	Engine, Power & Accessory Gearbox, Cover Assembly & Stepped Bearing Cage - Enlarge Gear Access Aperture	02-28-81	2	06-05-86	11-30-87	
72-3044	Engine, Turbine Exhaust Collector Inner Cone - Modify	11-30-80				
72-3045	Engine, Gearbox Housing - Assembly (Presto Castings only) - Modify to Eliminate Interference with Compressor	04-30-81				
72-3046	Engine, Compressor No. 1 Bearing & Retaining Nut - Replace	03-15-81	2	07-01-84		
72-3047	Cancelled Prior to Publication					
72-3048	Cancelled Prior to Publication					
A-72-3049	Engine, Turbine Inner & Outer P. T. Shafts - Replacement	04-15-81				
72-3050	Engine, Gearbox, Spur Adapter Gearshaft Forward Split Seal Piston Ring - Replace by Seal of Improved Material	05-15-82				
72-3051	Cancelled Prior To Publication					
72-3052	Engine, Compressor Front - Bearing Housing, Change	09-30-82				

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3053	Engine, Turbine P. T. or Inner & Outer Shafts & Inner Coupling Nut Electroless Nickel Plate Instead of Sermetel W or Al- seal 500	Cancelled- REF: CEB-A- 72-3119				
72-3054	Engine, Gearbox Scavenge-Oil Transfer Tube - Replace by Tube Incorporating a Mesh Screen	09-16-81	1	11-30-81		
72-3055	Engine, Gearbox, Inspect- Oil Delivery Tube (Piccolo) for Burrs Once Only	07-15-81	1	04-15-83		
A-72-3056	Engine, Turbine, Fourth-Stage Nozzle -Inspect	06-08-81	5	02-15-95		
72-3057	Engine, Compressor Shroud Housing - Epoxy Paint Coating Over A1-Polyester Lining	Cancelled- REF: CEB 72-3093				
72-3058	Engine, Turbine, P. T. Inner Shaft - Replace by Shaft with Increased Pilot Diameter O.D.	12-15-81	2	12-02-85		
72-3059	Engine, Compressor & Gearbox - Assemblies - Modify to Roller No. 2 1/2 Bearing Configuration	06-30-82	7	10-31-94	11-30-86 11-30-87	
72-3060	Engine Magnetic Plugs	01-15-82			08-01-82	
72-3061	Engine, G. P. Turbine Support - Power Turbine Support and Seal Assy Break Edge Hole	06-15-84				
72-3062	Cancelled Prior to Publication					
72-3063	Engine Gearbox Power Train Drive Gear Bearing Journals - Modify by Adding Grooves	Cancelled		06-30-97		
72-3064	Cancelled Prior to Publication					
72-3065	Engine, Turbine Assembly, Power Turbine Oil Sump Cover - Modify	05-09-83	3	09-20-85		
72-3066	Engine, Flight Approved Covers	11-30-82	2	04-30-85		
72-3067	Engine Conversion 250-C30 to 250-C30S	08-30-82	2	08-15-83		
72-3068	Engine Turbine & Exhaust Collector Support Assy - Add Gearbox Breather Port Vent and Compressor Bleed Valve Vent	02-28-83	2	09-16-85		
72-3069	Engine Power and Accessory Gearbox Cover Assembly Pinion Boss Gear Access Aperture - Round Edges	05-15-82				

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3070	Engine Compressor Assembly, Rear Laby- rinth Seal Replace Suspect Seal at next Overhaul	09-30-82				
72-3071	Cancelled Prior to Publication					
72-3072	Engine, Turbine, Retaining Ring Nos. 6 and 7 Bearings - Replace	10-15-82	1	04-15-83		
72-3073	Engine Gearbox Assembly - Replace No. 2 1/2 Cage Studs As Repair Action	05-27-83	2	01-15-88		
72-3074	Engine, Gearbox Lubrication System - Change Oil Pump Attachments Bolts	09-30-82	1	11-15-83		
72-3075	Engine, Gearbox Oil Filter Differential Pressure Indicator - Change	01-15-83	1	12-02-85		
72-3076	Cancelled Prior To Publication					
72-3077	Engine, Gearbox, Cover Assembly Scavenge and Pressure Oil Transfer Tube Parts Lead-in Chamfer - Modify	10-15-82				
72-3078	Engine, Compressor Rear Support and Diffuser Assy, Indexing Pin - Replace	11-30-83				
72-3079	Engine, Turbine Assembly - Add - Access Holes to Horizontal - Firewall Shield As- sembly	04-29-83	1	05-01-88		
72-3080	Cancelled Prior to Publication					
A-72-3081	Engine Compressor Mount Assy - Inspect for Cracks	09-15-82				
72-3082	Cancelled Prior to Publication					
72-3083	Engine, Quick Disconnect Magnetic Drain Plugs - Install	01-31-79	9	11-07-19		
72-3084	Cancelled Prior to Publication					
72-3085	Engine, Compressor - New - Compressor Mount Assembly	04-15-83	2	03-15-86	11-30-86	
72-3086	Engine, Gearbox Assembly, Oil Pressure Jet - Add Second Jet Hole	04-10-85				
72-3087	Cancelled Prior To Publication					
72-3088	Cancelled Prior to Publication					
72-3089	Engine, Gearbox - New Bushing For Oil Check Valve	04-22-83	2	06-30-93		

#### COMMERCIAL ENGINE BULLETIN INDEX

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3090	Cancelled Prior to Publication					
72-3091	New Scroll to Air Tube Flange - Adapter Assembly	04-15-83	1	04-09-85		
72-3092	Cancelled Prior to Publication					
72-3093	Engine - Compressor Assy - Compressor Shroud Housing, Modified to Incorporate Aluminum Graphite Coating	05-20-83	4	08-01-88		
72-3094	Engine, Turbine, New No. 8 Bearing	04-22-83	1	05-15-84		
72-3095	Engine, Gearbox Idler Gearshaft Bearings - Replace	04-22-83	1	02-01-86		
72-3096	Engine, Turbine - Exhaust Collector Modifications	06-01-83	4	04-15-93	11-30-86 11-30-87	
72-3097	Engine Gearbox Assembly - Scavenge Oil Pump Cover Assembly - Add Loctite to Gearshafts	04-22-83				
A-72-3098	Engine, Power and Accessory Gearbox Cover and Housing Assy, Magnetic Plug	06-01-84	6	10-31-97	04-30-85	
72-3099	Engine Turbine Assy - 4th-Stage Nozzle - Reidentify	09-30-83	2	10-15-93		
A-72-3100	Engine, Compressor Assembly, Spur Adapter Gearshaft - Modify by Adding Three Slots in Bore and Plugging Oil Feed Hole	04-22-83	2	09-01-94	11-30-86 11-30-87	
72-3101	Engine, Turbine Assembly 1st- & 2nd- Stage Nozzle Assemblies Outer Band Re- inforcing Ring and Rope Packing	05-16-83	6	10-15-91		
72-3102	Engine, Turbine - New No. 5 - Bearing Oil Seal	Cancelled				
72-3103	Engine Turbine Assembly - Turbine to Compressor Coupling Shaft - Replace	Cancelled				
72-3104	Engine, Gearbox, Bearing Manufactured by Marlin-Rockwell Corp Inspect Separator	09-30-82	1	12-15-83		
72-3105	Cancelled Prior to Publication					
72-3106	Cancelled Prior to Publication					
72-3107	Engine, Turbine - Replace First-Stage Turbine Wheels with Small Trailing Edge Fillet Radius	07-01-83				
A-72-3108	Engine, Turbine - Inspect Turbine Shafting & Replace Spur Adapter Gearshaft O-Ring	08-01-83	3	09-15-85	11-30-86	

#### COMMERCIAL ENGINE BULLETIN INDEX

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3109	Engine, Turbine Assembly, Gas Producer Rotor Assembly - Replace Tie Bolt by Tie Bolt of Improved Strength	02-15-85	3	01-15-90	02-28-90 02-28-92 02-28-94	
72-3110	Engine, Vertical Firewall Assembly - Modify	04-20-85				
72-3111	Engine, Turbine Assembly, Exhaust Collector Vent Tube Doublers	08-01-88	2	10-15-91		
72-3112	Cancelled Prior to Publication					
72-3113	Cancelled Prior to Publication					
72-3114	Turbine Assy, Turbine Nozzle Shield Positioning Plug - Modify	02-15-84	1	05-15-86		
A-72-3115	Engine, Outer Combustion Case Assy - Add Reinforcement Wire Patch	05-15-84	4	09-01-94	01-31-86 06-30-86	
72-3116	Cancelled Prior to Publication					
72-3117	Cancelled Prior to Publication					
72-3118	Cancelled Prior to Publication					
A-72-3119	Engine, Turbine Assembly, Inner and Outer Power Turbine Shafts Thicker Electroless Nickel Plate	10-16-85	4	11-24-08	08-31-92 08-31-95	
72-3120	Model 250 Engine or Module Conversion Authorization	09-30-85	12	03-06-19		
72-3121	Engine - Accessory Gear Box Assembly - Improved Through Bolt Attachment Ar- rangement for the Idler Gear	10-30-86	2	11-01-88		
72-3122	Engine Turbine Assy, New Fourth-Stage Nozzle	08-01-84	1	04-26-85		
72-3123	Engine, Gearbox Oil Transfer Tubes - Replace and Flanged Bushings - Install	06-05-87	2	12-01-88		
A-72-3124	Engine, Turbine Assy, External Energy Absorbing Ring - Installation	11-15-84	2	09-01-94		
A-72-3125	Engine, Turbine Assy, Horizontal Firewall Shield Assy Modification for Installation of the External Energy Absorbing Ring	11-15-84	3	09-01-94		
72-3126	Engine, Accessory Gearbox Assembly, Flanged Studs for Compressor Mounting Boss Repair	12-30-89	3	02-04-08		
A-72-3127	Engine, Gas Producer Turbine Assy Additional Assembly and Inspection Proce- dures	09-14-84	4	05-01-89		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
A-72-3128	Engine, Turbine Assembly, Modification of Gas Producer Support Incorporation of the Internal Energy and Absorbing Ring	11-15-84	2	09-01-94	11-30-87	
72-3129	Cancelled Prior to Publication					
72-3130	Cancelled Prior to Publication					
A-72-3131	Engine, Turbine Assembly, Second-Stage Nozzle - Increased Clearance in the Labyrinth Seal	11-15-84	2	09-01-94		
A-72-3132	Engine, Turbine Assembly, New 2nd-Stage Turbine Wheel	02-01-85			11-30-86	
72-3133	Cancelled Prior to Publication					
A-72-3134	Engine, Turbine Assembly, Turbine to Compressor Coupling Shaft - Replace	01-03-85	2	09-15-85	11-30-86	
A-72-3135	Engine, Turbine Assembly, Turbine to Compressor Coupling Shaft - Replace	04-15-85	3	09-01-94	03-06-86 11-30-87	
A-72-3136	Engine, Turbine Assembly, External Energy Absorbing Ring - Removal	07-31-85	1	09-01-94		
A-72-3137	Engine, Turbine Assembly, New Second- Stage Turbine Wheel	02-15-85	2	08-10-87	11-30-87	
72-3138	Engine, No. 6, 7, and 8 Bearing Lube Oil Supply Line - Check Valve Addition	06-23-86				
72-3139	Cancelled Prior to Publication					
72-3140	Cancelled Prior to Publication					
72-3141	Cancelled Prior to Publication					
72-3142	Engine, Turbine Assembly, Third-Stage Nozzle Assembly, Modify	07-15-87				
A-72-3143	Engine, Turbine Assembly-Inspect Turbine Shafting and Replace Spur Adapter Gear- shaft O-Ring	09-15-85	1	09-01-94		
72-3144	Cancelled Prior to Publication					
72-3145	Engine, Accessory Gearbox Assembly, Gearbox Cover Rework For New Fuel Control and Oil Pump Gearshaft	01-16-86	1	10-18-99		
A-72-3146	Engine, Turbine Assembly - Inspection Of Splined Adapter Locknut Torque	10-01-85	1	07-15-92		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3147	Engine, Compressor Shroud Housing - Epoxy Paint Coating Over Al-Polyester Lining	02-03-86				
72-3148	Engine, Turbine Assembly, Number 8 Bearing Oil Film Dampening	Cancelled- REF: CEB 72-3173 and 72-3174				
72-3149	Cancelled Prior to Publication					
72-3150	Engine, Turbine Assembly, 2nd-Stage- Nozzle Inner Ring - Replace	08-1-88	1	11-15-88		
72-3151	Engine, Power Turbine Support Assembly and Sump Cover Assembly - Rework	10-27-86	1	08-15-87		
72-3152	Engine, Power and Accessory Gearbox, Installation of Increased Capacity Oil Pump	11-01-88	5	12-15-94		
72-3153	Engine, Turbine Assembly, Gas Producer Support Modification For Internal Energy Absorbing Ring Support Pads	12-15-86	5	05-30-97		
72-3154	Engine, Accessory Gearbox Oil Filter Housing, Add Bronze Bushings to "Oil In", "Oil Out" and "Bypass" Ports	07-01-89	4	11-05-99		
72-3155	Cancelled Prior to Publication					
72-3156	Cancelled Prior to Publication					
72-3157	Engine, Gearbox Assembly, Installation of New 3 and 4 Roller Bearings	Superseded by CEB 72-3193				
72-3158	Engine, Turbine Assembly, Installation of the Number 5 Bearing Labyrinth Seal	05-01-89	5	07-06-15		
A-72-3159	Engine, Turbine Assembly - Gas Producer Pressure Oil Tube Replacement	Superseded by CEB-A- 72-3165				
72-3160	Engine, Turbine, Pressure Oil Check Valve Clamping Spacer - Replace	08-01-88			07-31-90	
72-3161	Engine, Turbine, Gas Producer Support, Modify Pilot Fit	05-01-89	2	10-30-92		
72-3162	Cancelled Prior to Publication					
72-3163	Cancelled Prior to Publication					
72-3164	Engine, Turbine Assembly, New Optimized Power Turbine Sump Clearances	Cancelled				

#### COMMERCIAL ENGINE BULLETIN INDEX

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
A-72-3165	Engine, Turbine Assembly - Gas Producer Pressure Oil Tube Replacement	08-31-87	1	09-01-94	12-10-87 07-01-88	
72-3166	Gearbox Assembly, Deletion of 15 H.P. Spare Accessory Drive System, Optional	04-15-83	3	12-30-90		
72-3167	Engine, Accessory Gearbox, Torquemeter Gearshaft Bore, Add Chamfer	03-15-89	1	07-15-90		
72-3168	Engine, Turbine Assembly, First-Stage Nozzle Diaphragm Locating Key Welds - Modify	11-15-90	2	04-15-93		
72-3169	Engine, Turbine Assembly, Fourth-Stage Nozzle Diaphragm Locating Key Welds - Modify	10-16-89	2	11-15-96		
72-3170	Engine, Compressor Assembly No. 1 Oil Damped Roller Bearing, Install	Superceded by CEB 72-3242				
72-3171	Engine, Compressor Assy, Alternate Compressor Shroud Housing Coating	10-01-88	3	08-15-97		
72-3172	Engine, Combustion Liner, Modify to Improve Burner Outlet Temperature (B.O.T.) Profile	Cancelled				
72-3173	Engine, Turbine Assembly, Gas Producer #8 Bearing Thrust Plate - Replace	Superseded by CEB 72-3189				
72-3174	Engine, Turbine Assembly, Number 8 Bearing Oil Film Dampening	Superseded by CEB 72-3190				
72-3175	Engine, Turbine Assembly, New Gas Producer Turbine Tiebolt Spanner Nut	Cancelled				
72-3176	Engine, Compressor Assembly, Diffusr Replacement for Hot Day Performance Enhancement	03-31-90	7	01-06-99		
72-3177	Engine Gearbox Assembly, Oil Pump Body Assembly, Inspection and Rework	12-31-89	2	02-15-95		
72-3178	Engine, Turbine Assembly, Remove Bracket From Exhaust Collector	07-31-89	1	07-20-90		
72-3179	Cancelled Prior to Publication					
A 72-3180	Engine, Turbine Assy, Alseal Coating of Power Turbine Inner and Outer Shafts	02-28-90	7	02-29-96	08-31-92 08-31-95	
72-3181	Engine - Gearbox, Rework of Electrical Harness Connector Bracket	10-01-91				

#### COMMERCIAL ENGINE BULLETIN INDEX

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3182	Engine, Accessory Gearbox, Rework to Add New Scavenge Oil Pickup Tube	11-01-91	1	12-15-94		
72-3183	Engine, Turbine Assembly, Third-Stage Nozzle Assembly, Modify	09-30-90				
72-3184	Engine, Compressor Assembly, Compressor Scroll, Reinforcing Wire Screen, Add	Cancelled				
72-3185	Engine, Compressor Assembly, Addition of Puller Groove for Removal of No. 2 Bearing	07-31-92	1	12-15-94		
72-3188	Engine, Turbine Assy., 2nd-Stage Turbine Nozzle Radial Clearance - Modify	04-15-93	2	10-31-94		
72-3189	Engine, Turbine Assembly, Gas Producer No. 8 Bearing Thrust Plate - Replace	Cancelled- Superseded by CEB 72-3199				
72-3190	Engine, Thrust Assembly, No. 8 Bearing Oil Film Dampening	Cancelled- Superseded by CEB 72-3199				
72-3191	Engine, Compressor Assembly, Shroud Rework and Identification for Use on 250-C30G/2 Engines	10-15-93	2	04-15-98		
72-3192	Cancelled Prior to Publication					
72-3193	Engine, Gearbox Assembly, Installation of New No. 3 & 4 Roller Bearings with Tabbed Outer Race & Cage	01-31-95	3	11-15-96		
72-3194	Engine, Gearbox Assembly, Replacement of Front Bearing Support - Rework	10-15-95				
A-72-3195	Engine, Turbine Assembly, Inspection and Rework of No. 5 Bearing Snap Ring Groove in Exhaust Collector - Rework	02-15-93				
72-3196	Engine, Turbine Assembly, Authorization to Reidentify Semi-Finished 2nd-Stage Nozzles	12-31-93	7	03-29-18		
72-3197	Engine - Conversion of 250-C30R to C-30R/1	Cancelled				
72-3199	Engine, Turbine Assembly, Release of New No. 8 Dampened Bearing with Increased Dampening Capacity	10-31-94	4	04-24-19		
72-3200	Engine, Compressor Assy, Rework of Compressor Front Shroud Housing - In- creased Inducer Bleed Slot and New Con- tour	04-15-94	4	03-25-99		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3201	Engine, Gearbox Assembly, Rework of 250-C30G/2 Front PTO Output Flanges to Incorporate Anchor Nuts	08-15-95				
72-3202	Engine, Inspection for Proper Clamping	05-15-95			12-31-95	
72-3203	Engine, Turbine Assy, Release of New Turbine Assy for 250-C30G/2 Engine	06-30-95				
72-3204	Cancelled Prior to Publication					
A 72-3205	Engine, Quick Disconnect Magnetic Plugs - Inspect Locking Pins and Insert Slots for Wear	Cancelled				
72-3206	Engine, Accessory Gearbox, Rework of the Gearbox Cover Without Requiring the Installation of the Increased Capacity Pump or Longer Scavenge Tube	06-15-95	1	02-12-14		
72-3207	Engine, Turbine Assembly, Replacement of Third-Stage Nozzle for Improved Performance	11-07-96	3	06-22-01		
A 72-3208	Engine, Turbine, Inspection of First-Stage Nozzle Shield Dome Detail for HMI or Over- haul	01-15-96	2	05-15-99		
72-3209	Engine, Turbine Assembly, Rework of Horizontal Fireshield, (23057784)	10-31-96	3	09-19-01		
72-3210	Engine, Turbine, Release of No. 5 Labyrinth Seal Air Tube Slip Joint - Replacement	10-31-96				
72-3211	Engine, Compressor and Turbine Assembly, Performance Improvement	07-30-97	1	07-31-98		
72-3212	Engine, Gearbox Assembly, Oil Delivery Tube, Improved Targeting	Cancelled				
72-3213	Engine, Compressor, Release of Improved Surge Margin Hardware for 250-C30 En- gines Installed in Boeing Aircraft Only	06-30-97	2	12-17-04		
72-3214	Engine, Gearbox, Output Duplex Drive Bearing Shimming Inspection, 250-C30G/2 and 250-C40B Only	05-15-97				
72-3215	Engine Assembly, Electrical System Clamping - Clamp Size Change	11-30-97				
72-3216	Cancelled Prior to Publication					
A-72-3217	Engine, Accessory Gearbox Assembly - Improved No. 3 and No. 4 Bearings - Install	01-15-98	4	10-04-01		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3218	Engine, Compressor Assembly, Release of New Number One Bearing Housing To Reduce One Hertz Whine	12-21-98	1	05-12-08		
72-3219	Engine, Turbine Assembly, Horizontal Fireshield - Replace	04-30-98	2	11-30-98		
72-3220	Engine, Turbine Assembly - Reidentification of Fourth Stage Turbine Wheel	12-15-97				
72-3221	Engine, Turbine Assembly - Gas Producer Turbine Support - Replace	07-31-98	2	02-10-14		
72-3222	Cancelled Prior to Publication					
72-3224	Engine, Compressor Assembly - New Shroud Coating	02-15-98	1	08-07-98		
72-3225	Engine Assembly - Clamping Configuration - Revise	04-15-98				
72-3226	Engine, Power and Accessory Gearbox, PTO Gearshaft Grooves - Add	06-10-98	1	11-18-98		
72-3227	Engine, Combustion Section, Release of New Reduced Smoke Combustion Liner - Replace	12-15-97	3	07-10-19		
72-3228	Engine, Compressor Assembly - Removal of Compressor Vent Gaskets	02-15-98	1	03-31-98		
A-72-3229	Engine, Turbine Assembly - Recall of Certain 250-C28 and 250-C30 Series Combustion Liners	05-07-98				
72-3230	Engine, Compressor Assembly, Installation of 250-C30R/3 Compressor on a 250-C30R/1 Engine	04-30-98	1	08-20-99		
72-3232	Engine, Compressor Assembly - Release of New Increased Thickness Compressor Scroll	Cancelled				
72-3234	Engine, Compressor Assembly - Release of New Number One Bearing Scavange Tube	11-17-98				
72-3235	Engine, Gearbox Assembly - Release of New Spare Pad Cover to Prevent Oil Leakage	02-16-99				
A-72-3237	Canceled Prior to Publication					
72-3238	Engine, Turbine Assembly - Recoating Of Inner Power Turbine Shaft	11-22-99	2	02-22-10		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3239	Engine, Compressor - Scroll Assembly, Replacement	07-30-97	2 Reissue	03-17-00		
72-3240	Engine, Compressor Assembly - Compressor Rear Support - New Stationary Seal Coating	02-27-98	2	10-12-99		
72-3242	Engine, Compressor Assembly - Release of New Number One Bearing Assembly to Reduce One Hertz Whine	12-14-98	1	08-12-99		
72-3244	Engine, Gearbox Assembly - Release Of New Helical Torquemeter Gearshaft Assemblies and Internal Retaining Rings (Damper)	11-05-99	3	05-03-10		
72-3245	Engine, Turbine Assembly - Release of New Engine Rear Mount Assembly	06-30-00	2	06-16-14		
A-72-3247	Engine, Compressor Assembly - New Compressor Scroll	06-09-00	2	10-17-00		
A-72-3248	Engine Assembly - Inspection Of The New Self-Sealing Magnetic Chip Detectors	Cancelled				
A-72-3249	Engine, Turbine - One-Time Inspection For Overtemperature Damage	02-23-00				
72-3250	Engine, Compressor Assembly - Release of New Increased Thickness Compressor Scroll	06-09-00	1	03-21-02		
A-72-3252	Engine, Turbine - Inspection of 1st-Stage Nozzle Shield Dome	03-29-00	9	04-30-18		
72-3256	Engine Assembly - One Time Inspection Of -30 Engine Inlet Plates	05-31-01				
72-3258	Engine - Conversion Of 250-C30R/3 To -C30R/3M	02-13-02	2	03-10-15		
72-3259	Engine, Turbine Assembly - Release of Third-Stage Nozzles For C30, C30G, C30G/2, C30M, C30P, C30R, C30S and C30U Engines	04-23-02	1	08-15-11		
72-3260	Engine, Main Accessory Gearbox - Release of Rework And Reidentified Lip Seals	04-25-02				
A-72-3261	Engine, Compressor Assembly - Replacement of Splined Compressor Rotor Adapter	06-21-02				
72-3264	Engine, Compressor Assembly - Release of New Compressor Rotor Assembly	10-29-03	1	02-07-11		

#### COMMERCIAL ENGINE BULLETIN INDEX

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3265	Engine, Oil Pump Assembly - Release of New Oil Pump Gear Shafts	06-22-04				
A-72-3266	Engine, Turbine Assembly - Inspection of 4th-Stage Turbine Wheels (23066744)	10-01-03	3	02-03-04		
72-3267	Engine, Gearbox Assembly - Release of New Pinion and Torquemeter Gear Set, Low Speed Gearbox	10-13-04				
A-72-3268	Engine, Turbine Section - Inspection of Rolls-Royce Model 250-C30 and 250-C30S (Twin Engine Application) Third-Stage Wheels (6898663)	05-03-04	2	04-13-15		
72-3269	Engine, Turbine Assembly - Release of New 2nd-Stage Turbine Splined Adapter and Spline Lock Nut	08-24-04	1	04-19-05		
72-3270	Engine, Gearbox Assembly - Replacement of Breather Gear Seal	02-07-05				
72-3271	Engine, Gearbox Assembly - Release of New Centrigugal Breather Gearshaft with Molybdenum Coating	02-09-07				
A-72-3272	Engine, Turbine Assembly - New Threshold Event Recording and New Steady-State Operation Avoidance Range Limit	Cancelled				
72-3273	Engine, Compressor Rear Support Assembly - Inspect #2 Bearing Lock Key Slot Radii	09-20-05	3	05-25-09		
A-72-3274	Engine, Gearbox Assembly - Inspection And Rework of Gearbox Housings	06-30-05				
A-72-3278	Engine, Turbine Assembly - Power Turbine Outer Shaft	10-09-06	3	01-19-09		
72-3279	Engine - Gearbox Asembly - New Power Gears	08-17-07	5	02-08-17		
72-3280	Engine - Gearbox Asembly - New 15 HP Spare Drive Gearshaft	08-08-07	2	02-22-08		
72-3281	Engine - Turbine - Power Turbine Support Rework and Reidentification on Series IV Engines	06-20-14	1	03-24-17		
72-3284	Engine, Turbine Assembly - Refurbishment of Compressor Labyrinth Seal Material	03-21-11				
72-3285	Engine, Compressor Assembly - Repleacement fo N0. 2 Bearing	04-11-11	1	08-08-11		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3287	M250-C47B, C47M, C30R/3M Series Engine Enhancement Kit	04-30-12	3	11-28-18		
72-3288	Engine Gearbox Asembly - Inspection of Gearbox Cover	05-07-12				
72-3289	Engine, Accessory Gearbox Assembly - Improved Torquemeter Thrust (Ball) Bearing - Install	12-14-12	1	08-12-13		
72-3290	Engine, Turbine Assembly - 2nd-stage Turbine Wheel Inspection and Peen	03-18-13	2	12-18-13		
72-3291	Engine, Series IV Diffuser Assembly - Braze Inspection	06-17-13	1	03-24-14		
72-3292	Engine, Assembly - Inspection of Mag Plugs to Detect Metal Generation from the No. 2 Bearing	03-04-13	2	03-24-14		
A-72-3295	Engine - Spur Adapter Gearshaft, Retaining Ring	05-14-14	2	07-29-14		
A-72-3296	Engine - Turbine Assemby - Inspection of 3rd Stage Turbine Wheels 6898663	06-27-14	3	01-04-17		
A-72-3297	Engine, Compressor Assembly - Inspection of Front Support P/N M250-10051, M250-10052, M250-10059, M250-10060	07-29-14	1	08-22-14		
72-3298	Engine - No. 5 Bearing Retaining Ring Replacement	09-03-14	1	07-13-15		
72-3299	Engine - Gearbox Assembly - Replacement of Oil Delivery Tube (Piccolo Tube)	01-20-15	5	04-12-19		
72-3300	Engine - Turbine, Removal of Aft Combustion Drain Valve	11-17-14				
72-3301	Engine - No. 8 Beaaring Manufactured by NHBB	03-27-15				
A-72-3303	Engine, Combustion Assembly- Inspection of Outer Combustion Case P/N M250-10404	09-01-16	3	02-02-17		
72-3304	Gearbox Housing PTO Bearing Support Oil Passage	04-20-17	1	10-13-17		
A-72-3305	Engine, Turbine Section- Replacement of Rolls-Royce Single-Piece Wire Patch Outer Combustion Case Assemblies	10-23-18				

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
72-3306	M250 Gearbox Oil Check Valve, Guide, Poppet, Check Valve Replace P/N 23085911 and 6898840 with New P/N M250-10893 or P/N M250-10894	10-16-19	1	01-08-20		
72-3307	Engine, Combustion Section- Replacement of Combustion Liner	05-10-18				
72-3308	Engine, Conbustion Assembly- Replacement of Outer Combustion Case P/N 23030911	02-09-18				

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
73-3001	Engine Fuel and Control, Fuel Control and Governor Assemblies Screened Orifices - Replace	08-15-80	2	06-15-98		
73-3002	Engine, Fuel and Control - Start - Acceleration Flow Schedule Adjuster - Add	01-30-80	1	08-30-80		
73-3003	Fuel System, Gas Producer Fuel Control - Modify	04-17-79	1	07-09-79		
73-3004	Engine, Fuel and Control, - Pc Air Filter - Add	05-15-80	5	05-15-82	10-31-82	
73-3005	Engine, Fuel Control, N <sub>2</sub> Overspeed and Compressor Bleed Control Solenoids Plunger Spring - Replace	09-30-79				
A-73-3006	Engine, Fuel and Control, ${\rm N_2}$ Overspeed Control - Replace	03-14-79	2	09-01-94		
73-3007	Engine, Fuel and Control, - L. P. Fuel Filter Rework	04-17-79	1	06-29-79		
73-3008	Engine, Fuel and Control, N <sub>2</sub> Overspeed Control - Replace	06-30-80	2	05-15-81		
73-3009	Engine, Fuel and Control, Fuel Control Assembly Improved Lever and Bellows Assemblies - Modify	12-15-80	2	01-15-82		
73-3010	Engine, Fuel and Control, Fuel Control Assembly Governor Bellows Damper Rings - Add	05-15-80				
73-3011	Engine, Fuel and Control, L. P. Fuel Filter Assembly Bowl Retaining Bolt - Add Re- taining Ring Keeper	07-15-81	1	03-30-82		
73-3012	Bendix Power Turbine Governor Inspect Drive Shaft and Add Epoxy Bonding to Tor- sional Spring Drive Assembly	01-12-81	4	08-15-85		
73-3013	Engine, Fuel and Control, L. P. Fuel Filter Assembly - Inspect Filter Element Sealing Rings	12-23-80	1	03-31-81		
A-73-3014	Fuel and Control, - Fuel Pump to L. P. Filter Tubing Alignment, Tube Assemblies P/N's 6899l9l and 6895832 - One Time Inspection	07-17-81				
A-73-3015	Engine, Fuel and Control, N <sub>2</sub> Overspeed Control Assembly - Add Lockwashers to Ground Jumper Wire and Relocate	10-12-81	2	09-30-82		
73-3016	Cancelled Prior to Publication					

#### COMMERCIAL ENGINE BULLETIN INDEX

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
73-3017	Engine, Fuel And Control, Bendix Power Turbine Governor, Incorporation Of Governor Body Access Window	08-01-88				
A-73-3018	Engine, Fuel and Control, Disarm N <sub>2</sub> (Electronic) Overspeed Control System - 250-C30, C30M and C30P Single Engine Applications Only	11-10-81	2	11-30-83		
73-3019	Engine, Fuel and Control, Fuel Control Assembly Main Body Casting - Measure Wall Thickness at Torsion Shaft Bore End	Cancelled				
73-3020	Cancelled Prior to Publication					
A-73-3021	Engine, Fuel and Control, Bendix Fuel Control Assy's and Power Turbine Governor Assy's -Inspect Bushing Assy's	10-15-82			10-15-83	
73-3022	Engine, Fuel Control, Bendix Fuel Control Power Turbine Governor Assemblies - Add Filter Fittings	05-02-83	2	03-10-88		
73-3023	Cancelled Prior To Publication					
73-3024	Engine, Fuel and Control, Fuel Control and Governor Assemblies - Modify	03-15-84	2	07-15-87		
73-3025	Cancelled Prior To Publication					
73-3026	Cancelled Prior To Publication					
73-3027	Engine, Fuel Control Assy Relocate Px Orifice	07-31-83	1	08-15-85		
73-3028	Engine, Fuel and Control, Allied Bendix Fuel Control Assembly-Secondary Px Enrichment	05-06-86	1	09-15-88		
73-3029	Engine, Fuel, Lube And Air System, Fuel Control Unit Acceleration Governor Bellows Snubber - Add	05-01-88	1	11-01-89		
73-3030	Engine, Fuel and Control, Allied/Bendix Fuel Control - Model DP-VI-Increase In Intermediate Max Flow Stop Settings	09-15-88				
73-3031	Cancelled Prior To Publication					
A-73-3032	Engine, Fuel and Air System, Pc Scroll to Pc Filter Tube Assy - Inspection	06-23-86	3	04-15-92	07-31-86	
73-3033	Cancelled prior to publication					
73-3034	Engine, Fuel and Control, Improved Engine N <sub>2</sub> Overspeed Control Assembly - Install	04-01-88	2	10-01-91		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
73-3035	Engine, Fuel and Control System, Add Wire to Digital Control Unit Circuit Board	04-01-89				
73-3036	Cancelled Prior to Publication					
73-3037	Cancelled Prior to Publication					
73-3038	Engine, Power Turbine Governor Assembly, Allied/Bendix Model AL-ADI-Incorporation of Throttle Lever	05-01-88				
73-3039	Engine, Fuel and Control, Allied/Bendix Fuel Control - Model DP-VI Increase Low Maxi- mum Fuel Flow Setting	05-01-89				
73-3040	Engine, Fuel, Air, and Lube System, Additional Clamping	04-01-89	1	03-31-93	07-01-90	
73-3041	Cancelled Prior to Publication					
A-73-3042	Engine, Fuel and Control, Inspection of Certain Bendix Fuel Control Bellows Assemblies	08-01-88	2	09-01-94	10-01-88 07-01-89	
73-3043	Engine, Fuel and Control, Argo-Tech Fuel Pump, Machine Fuel Pump Gear Housing and Pump Cover Assembly	06-01-89	1	12-17-07		
73-3044	Cancelled Prior to Publication					
73-3045	Engine, Fuel and Control, Digital Supervisory Control Unit, Reidentify	06-01-89				
73-3046	Engine, Fuel and Control, Bendix Power Turbine Governor Conversion to High Speed Governor for Model C30G Installa- tions	01-15-90				
73-3047	Engine, Fuel and Control, Deletion of N <sub>2</sub> Electronic Overspeed System From Single Engine Applications	08-01-91	3	09-15-95		
73-3048	Cancelled Prior to Publication					
73-3050	Aviall Recall of Certain Bendix Power Turbine Governors	03-15-90	1	10-15-91	12-31-91	
73-3051	Cancelled Prior to Publication					
73-3052	Engine, Fuel and Control, Rework of N <sub>2</sub> Overspeed Control	03-15-91	1	11-15-91		
73-3053	Engine, Fuel and Control, Fuel Control Heater Kit, Replace Dummy Igniter Plug	04-30-93				

#### COMMERCIAL ENGINE BULLETIN INDEX

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
73-3054	Engine, Fuel and Control, Digital Supervisory Control Unit, Rework	12-01-90				
73-3056	Cancelled Prior to Publication					
73-3057	Engine, Fuel and Control, C30G PT Over- speed Governor, Addition of Counter- weighted PTG Governor Leveler Arm - Modify	09-15-91	1	04-30-92		
A-73-3058	Engine, Fuel and Control, Disarm N <sub>2</sub> (Electronic) Overspeed Control System - Multi-Engine Aircraft	03-15-92	2	11-15-93	06-30-92	
A-73-3059	Bendix Main Fuel Controls Used on Model 250 Series Engines - Application of NYE Synthetic Oil 608 to Beryllium Copper PC Bellows Assembly	Cancelled				
73-3060	Engine, Fuel and Control, Installation of New Throttle Positioning Spring - Replace	02-20-93				
73-3061	Replace Engine, Fuel and Control, Release of New Fuel Control With Stronger Bypass Valve Cover Retaining Screws - Modify	02-15-93	1	12-07-93		
73-3062	Engine, Electrical System Assembly - Release of New Electrical Harness and Im- proved Electrical Harness Clamping	02-28-94	1	12-15-97		
73-3063	Engine, Fuel and Control, Release of New Fuel Control Which Produces Four Fuel Settings - Modify	02-20-93	1	09-15-95		
73-3064	Engine, Fuel and Control, Removal of 3 Cubic In. Accumulator - Remove	10-30-93				
A-73-3065	Engine, Fuel Control, Inspection By-Pass Cover Screws and Replacement of All 250-C28 and 250-C30 Relief Valves	02-25-93				
73-3066	Engine, Fuel and Control, Digital Electronic Supervisory Control Assembly, Rework	10-20-92			03-31-93	
73-3067	Air Logistics Recall of Certain Bendix Power Turbine Governors and Fuel Controls	12-20-92			12-31-94	
A-73-3068	Engine, Fuel and Control, Fuel Control Bellows - Replace	11-18-93	4	10-09-01		
73-3069	Engine, Fuel Control, Replacement of Fuel Control Heater Manifold	11-15-93	1	01-3-94	01-31-94	
73-3070	Engine, Fuel and Control, Release of New Investment Casting Cover Assembly	11-30-94	2	09-15-97		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
73-3071	Engine, Fuel and Control, Removal of Magnetic N <sub>2</sub> Speed Pickup	03-15-94	2	08-15-94	12-31-94	
A-73-3072	Engine, Fuel And Control, Allied Signal Fuel Control - Model DP-V3 Inspection and Securing Torque Motor Max Adjustment Screw	03-31-94				
73-3073	Engine, Fuel And Control, Conversion of C30 PT Governor For Use On C30G/2 Engines	05-31-94				
73-3074	Engine, Fuel and Control, Additional Clamping Required Due to Release of New CECO Fuel Pump	01-31-96				
A-73-3075	Engine, Fuel and Control, Fuel Control By-pass Cover Screw Inspection	11-10-95	1	12-02-98		
73-3076	Engine, Electrical System, Install New Clamping	10-31-96	2	10-10-97		
73-3077	Engine, Fuel and Control, Release of New Design Shaft Seal for CECO Fuel Pump.	07-31-96				
73-3078	Engine, Fuel and Control, Drive Bearings - Replace	10-31-96				
73-3079	Engine, Fuel and Control, Fuel Control Assembly, Removal of Po Prime Dampening Orifice	06-30-96				
73-3080	Engine, Fuel and Control, Tube Assemblies - Replace	05-30-97				
73-3082	Engine, Fuel and Control, Fuel Control Heater - Washer Substitution to Improve Stud Protrusion	06-30-97				
73-3083	Engine, Fuel and Control, Fuel Control Po Prime Dampening Orifice Removal	04-07-97	2	10-28-98		
73-3084	Engine, Fuel and Control, Power Turbine Governor Drive Bearings - Replace	07-15-97	1	05-08-98		
73-3085	Engine, Fuel and Control - Fuel Control Drive Bearings - Replace	04-10-97	4	05-17-10		
73-3086	Engine, Fuel and Control, Fuel Control Stop Nut - Rework	08-31-97	2	10-13-99		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
73-3088	Engine, Fuel and Control, FADEC Assembly - Replace	06-30-97				
73-3089	Engine, Fuel and Control, Fuel Control Cut-off Valve Rework	08-31-97	1	06-09-00		
73-3090	Engine, Fuel and Control, Hydromechanical Unit (HMU) - Overspeed Solenoid - Re- place	09-15-97	4	12-19-00		
A-73-3091	Engine, Fuel and Control - CECO Engine Driven Fuel Pump - Internal Spline Inspec- tion	08-21-97				
73-3094	Engine, Fuel and Control, Hydromechanical Unit Assembly - Incorporation of a Screened Standpipe	11-26-97				
73-3095	Engine, Fuel Control - One-Time Inspection of Internal Components of the ECU	02-23-98	2	08-17-98		
73-3096	Engine, Fuel & Control - Revised Main and Accessory Harness Clamping	03-20-98				
73-3097	Engine, Fuel and Control - Electronic Control Unit (ECU) - Upgrade Software	04-09-98				
73-3098	Engine, Fuel and Control, Modification and Standardization of Fuel Control Unit Parts Lists	06-08-98				
73-3100	Engine, Fuel And Control - AlliedSignal (Bendix) Main Fuel Control - Incorporate One Piece Bypass Valve Sleeve	01-08-99	1	09-28-99		
73-3101	Engine, Fuel And Control - CECO MFP-264-1 & MFP-264-2 Fuel Pump - Replace	10-26-00 Cancelled 09-24-12				
A-73-3102	Engine, Fuel and Control - Honeywell Fuel Control Unit and Power Turbine Governor - Internal Spring Replacement	10-5-98	3	08-13-04		
A-73-3103	Engine, Fuel and Control - Inspection of HMU Drive Splines	11-06-98	4	12-02-03		
73-3104	Engine, Fuel and Control - Replacement of Tube Between The HMU And L/P Filter	02-10-00	1	04-19-00		
73-3105	Engine, Fuel and Control, Release of Flared Fuel Line Seals to Prevent Fuel Leaks	03-25-99				
73-3106	Engine, Fuel and Control - Release of New Bypass Retention Plate	04-20-01	1	11-15-02		

		Date	Revision	Date	Compliance	Compliance
CEB No.	<u>Subject</u>	<u>Published</u>	<u>Number</u>	Revised	Requirement	Completed
73-3107	Engine, Fuel and Control - Hydromechanical Unit (HMU) - Replace	04-28-99				
73-3108	Engine, Fuel and Control - Hydromechanical Unit (HMU) - Incorporate Screened P1 Nozzle, Adjustable Stop, And Other Product Improvements	11-26-02				
73-3109	Engine, Fuel And Control - Release Of New Electronic Control Unit (ECU)	06-23-00	3	07-01-04		
73-3111	Engine, Fuel and Control - Honeywell (Bendix/AlliedSignal) Main Fuel Control Units - One Time Inspection of Screws	04-06-01	1	05-13-02		
73-3112	Engine, Fuel and Control - Honeywell (Bendix/AlliedSignal) Power Turbine Gover- nor - Tee Filter Inspection	06-13-01				
73-3113	Engine, Control System - One Time Inspection For Proper Components	10-15-01	1	11-28-01		
73-3114	Engine, Fuel And Control - Honeywell Main Fuel Control Unit-Modification of Model DP-V1 Governor And Gas Turbine Fuel Control Parts List Number (2524944) To Parts List Number (2549092)	07-29-02				
73-3115	Engine, Fuel and Control - Power Turbine Governor Increased Durability Design	04-23-03				
A-73-3116	Engine, Fuel and Control - One Time Inspection of Power Lever (PLA) Signal of The HMU	05-08-03	1	05-23-03		
73-3117	Engine, Fuel and Control - Goodrich Engine Driven Fuel Pump Improved Drive Shaft Durability	04-07-04	3	03-06-19		
A-73-3118	Engine, Fuel Delivery - Release of New Fuel Nozzle	09-04-03	1	08-30-04		
A-73-3119	Engine, Fuel And Control - Hydromechanical Unit (HMU) - Incorporate Dual Element PLA Potentiometer	12-02-03				
73-3121	Engine, Fuel And Control - Inspection of Hydromechanical Unit (HMU) Drive Splines	01-07-05				
A-73-3122	Engine, Fuel And Control - One Time Inspection of The Hydromechanical Unit (HMU) P1 Nozzle	12-10-04	1	12-23-04		
A-73-3123	Engine, Fuel and Control -Hydromechanical Unit (HMU) Procedures For Checking P1 Nozzle Screen For Contamination	05-27-05		Cancelled 06-22-09		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
73-3125	Engine, Fuel And Control - Inspection of Fuel Filter Installation	02-09-07	1	12-07-07		
73-3126	Engine, Fuel and Control - Power Turbine Governor Increased Reliability	04-21-08	2	02-04-09		
73-3127	Engine, Fuel and Control - Goodrich Model EMC-35A Hydromechanical Unit (HMU) - One-Time Inspection of Relief Valve Wall Thickness	04-23-09 Cancelled 09-07-09				
73-3128	Engine, Fuel and Control - Hydromechanical Unit (HMU) - One-Time Torque of Metering Head Regulator Cover Bolts	03-29-10	2	12-20-10		
73-3129	Engine, Fuel & Control - Triumph (Goodrich) Electronic Control Unit (ECU) - Overspeed Protection System (OSPS) Power Supply Design Improvement	12-03-12	3	06-01-16		
73-3130	Engine, Fuel and Control - Hydromechanical Unit Assembly - Improved Design Power Lever Angle (PLA) and Metering Valve (MV) Potentiometers	09-20-10 Cancelled 11/1/10				
73-3134	Engine - Fuel Nozzle Spray Tip/Inner Air Shroud Replacement	09-09-13	2	10-20-14		
73-3135	Engine, Fuel & Control - Honeywell Main Fuel Controls - Replacement of the Bypass Valve Sleeve	04-09-12	2	12-01-15		
73-3136	Engine, Fuel & Control - Electronic Control Unit Assembly	08-23-13	3	07-22-16		
A-73-3137	Engine, Fuel & Control - Electronic Control Unit Assembly	01-07-13	4	03-28-16		
73-3138	Engine, Fuel & Control - Electronic Control Unit Assembly	09-16-13	2	04-30-19		
73-3139	Engine Fuel and Control - Power Turbine Governor Drive Bearing Replacement	01-20-14	1	09-08-14		
A-73-3140	Engine Fuel and Control - Overspeed Adapter	06-13-14	1	01-15-15		
73-3141	Engine Fuel and Control - New ECU Hardware and Software	10-30-14				
73-3142	Engine - Fuel and Control - TECS Engine Driven Fuel Pump Internal Spline Inspection	12-09-14	1	01-14-15		

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>	Compliance <u>Requirement</u>	Compliance Completed
73-3143	Engine, Fuel and Control- Honeywell Fuel Controls	01-15-15				
73-3144	Engine, Fuel and Control- New ECU Software (7301-FOST)	11-09-15				
73-3145	Engine, Fuel and Control- Power Turbine Governor New Drive Bearings	03-30-17	1	09-20-17		
73-3146	Engine, Fuel and Control- Fuel Control New Drive Bearings	10-26-17				

CEB No.	Subject	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
74-3001	Engine, Electrical - Start Counter Assembly - Removal/Installation	01-15-99	1	03-17-99		
74-3002	Engine, Ignition System - Relocation of Ignition Lead	08-04-00	2	06-04-02		
74-3003	Engine, Control System - Replace the Full Authority Digital Engine Control (FADEC) Exciter with the Non-FADEC Exciter on the FADEC Controlled 250 Engine Models M250-C30R/3, -C30R/3M	06-19-06	1	04-11-11		
74-3004	Engine, Ignition System- Repair or Replacement of Select Rolls-Royce P/N 6899093 (Unison P/N 10-614950-1) Ignition Exciters	06-23-17				

#### COMMERCIAL ENGINE BULLETIN INDEX

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
75-3001	Cancelled Prior to Publication					
75-3002	Air, Compressor Bleed Control System - Add	12-22-78				
75-3003	Air System, Compressor Bleed Valve Gasket - Add	08-31-79	1	12-15-79		
75-3004	Air System, Compressor Bleed Valve Screen - Add	07-31-79	1	03-28-80		
75-3005	Air System, Compressor Bleed Valve Orifices - Replace	08-15-79	2	08-30-80		
75-3006	Air System, Compressor Bleed Valve Installation - Modify	07-15-80	5	08-22-83		
75-3007	Air System, Compressor Bleed Valve Replumbed Configuration - Modify	09-30-80	1	01-15-82		
75-3008	Air System, Air Valve Assembly - Reduce Diameter of Piston	01-30-81			12-01-83	
75-3009	Air System, Compressor Bleed Valve - Add Vented Plug	03-15-81	1	01-15-82		
75-3010	Air System, Bleed Valve Assembly - Recalibrate	08-15-81	1	05-15-82		
75-3011	Air System, Compressor Bleed Valve Bellows - Replace	02-23-82	1	09-30-82		
75-3012	Air System, Bleed Valve Assembly Mounting Gasket - Replace by Stainless Steel	09-15-81	1	05-15-82		
75-3013	Fuel, Lube and Air System Solenoid Valve Assemblies Replace Rivets	01-30-83	1	03-30-85		
75-3014	Air System Compressor Bleed Valve Assembly Bellows Dampner - Scrap Blue Colored Dampner	09-30-82				
75-3015	Air System, Compressor Bleed Gasket - Replace with Larger Hole Gasket	03-15-83				
75-3016	Anti-Ice Air Tube - Replace	04-22-85				
A-75-3017	Engine, Fuel, Lube And Air System, Improved Strength Pc Filter Housing	02-15-88	3	02-01-10	10-31-88 04-30-89 10-31-89 04-30-90	
75-3018	Cancelled Prior to Publication					
75-3019	Cancelled Prior to Publication					

CEB No.	<u>Subject</u>	Date <u>Published</u>	Revision Number	Date <u>Revised</u>	Compliance Requirement	Compliance Completed
75-3020	Engine, Air System, Venting of Bleed Valve Discharge Air	10-31-89				
A-75-3021	Engine, Fuel, Lube and Air System, Relocated Pc Filter	08-01-88			06-01-89	
75-3022	Engine, Air System, Venting of Bleed Valve Discharge Air	10-31-89				
75-3023	Engine, Air System, Bleed Valve - Addition of A 6 Cu. In. Accumulator On All 250-C30 Engines Installed in McDonnell Douglas Helicopters	Cancelled				
75-3024	Engine, Air System - Bleed Valve With Improved Durability	01-30-03				
75-3026	Air System, Valve, Anti-Ice - Rework of Anti-Ice Valve	09-05-11				

#### **INSTALLATION BULLETIN INDEX**

IB No.	<u>Subject</u>	Date <u>Published</u>	Revision <u>Number</u>	Date <u>Revised</u>
3001	Kit, Fuel Flowmeter Installation	12-22-79	1	07-15-81
3002	Unassigned			
3003	Engine Fuel and Control, Fuel Control Heating - Customer Option	Cancelled		
3004	Engine, Fuel and Control Fuel Control Heating Kit - for Fuel Controls with Relocated Px Orifice - Customer Option	Superseded by IB 3007		
3005	Engine, Fuel and Control, Fuel Control Heating Kit - Customer Option	Superseded by IB 3007		
3006	Engine, Installation of Bell 206L III Engines in 206L IV Aircraft	10-30-93		
3007	Engine, Fuel and Control, Release of Redesigned Fuel Control Heater Kit - Customer Option	11-15-93	3	03-08-10
3008	Engine, Fuel and Control - Installation of Power Turbine Governor Lock-Out Kit on 250-C30P Engines Installed In Bell 206L-3 and 206L-4 Air- craft	07-05-00		
3011	Conversion 250-C30P(WO) Engine to 250-C30P(BO) Engine for Installation in Eurocopter BO105 Aircraft	08-11-08		