



Rolls-Royce

**Rolls-Royce Corporation
M250-C20**

**COMMERCIAL SERVICE
LETTER
(CSL)**

**Technical Publications
Index**

March 3, 2020

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1001	M250 Authorized Maintenance Centers (AMCs), Publications, Rolls-Royce Telephone Contacts, Warranty, Training, and Unapproved Parts	Reissue 03-31-97	11	06-11-18
1002	Approved Lubricants-Engine Oil System	Cancelled-Ref: Ops. And Maint. Manual		
1003	Fuels Approved for use in The 250-C20 Series Engines	Cancelled-Ref: Ops. And Maint. Manual		
1004	Time Between Overhauls	Cancelled-Ref: Ops And Maint. Manual		
1005	250-C20 Series Engine Time Limited Parts	Cancelled-Ref: Ops. And Maint. Manual		
1006	Compressor Installation 250-C20 Engine	Cancelled-Ref: Ops. And Maint. Manual		
A-1007	Dual Element Fuel Pump Drive Shaft Inspection	11-16-72	4	09-01-94
1008	O-Ring Added Between Oil Filter Element And Standpipe	Cancelled-Ref: Illus. Parts Catalog		
1009	Early Lightoff or Afterfire	01-20-72		
1010	Field Inspection Instructions For Determination Of Proper Sealing Of The Throttle Shaft	Cancelled		
1011	CECO Field Service Information	01-21-72	3	10-15-93
1012	CECO Fuel Control Idle Speed Adjustment	Cancelled		
1013	CECO Fuel Control Throttle Shaft O-Ring Seal Replacement	08-25-72	3	03-31-76
1014	AVGAS Mixture Using 100/130 Aviation Gasoline With Commercial Jet A Turbine Fuel In Cold Weather Operation	Cancelled-Ref: Ops. And Maint. Manual		
1015	Compressor Salt Water Contamination Removal	Cancelled-Ref: Ops. And Maint. Manual		
1016	Oxide Discoloration of Hot Section Components	02-13-73		
1017	Maximum Continuous Power and Maximum Cruise Power Ratings	02-13-73		

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1018	Maintenance Action-Engine Operation Beyond Limit of 107°C Oil Temperature.	Cancelled-Ref: Ops. And Maint. Manual		
1019	Water Washing the Compressor in Cold Weather	Cancelled-Ref: Ops. And Maint. Manual		
1020	Contamination Removal (Water Rinse) Instructions <u>Using Water Only</u>	Cancelled-Ref: Ops. And Maint. Manual		
1021	Required 250-C20 Field Inspections	Cancelled-Ref: CSL-1007		
1022	Starter Generator and Starter Generator Gearshaft Mating Spline Wear	Cancelled-Ref: Ops. And Maint. Manual		
A-1023	Extreme Turbine Outlet Temperature Effects on Turbines	08-01-73	4	09-05-75
1024	Inspection of MC-40 Fuel Control And Governor Speed Rotor Weights	10-25-73		
1025	Single Element Fuel Pump Shouldered Drive Shaft Inspection	Cancelled-Ref: Ops. And Maint. Manual		
1026	Model 250 Engine Log Book	Cancelled 03-24-08		
1027	250-C20B Engine Time Between Overhauls	Cancelled-Ref: Ops. And Maint. Manual		
1028	250-C20B Engine Life Limited Parts	Cancelled-Ref: Ops. And Maint. Manual		
1029	Fuel System Leakage - Inspection And Trouble Shooting	Cancelled-Ref: Ops. And Maint. Manual		
1030	250 Series Engines - Cost Effect of Modular Overhaul	Cancelled-Ref: Ops. And Maint. Manual		
1031	250-C20 Engine Ground Starting Above 5000 Feet	07-08-74		
1032	Purging of the CECO Fuel Control	07-15-74		
1033	Bleed Valve Cleaning	Cancelled-Ref: Ops. And Maint. Manual		
1034	CECO Fuel Control Flushing Procedure to Remove Suspected Internal Contamination	01-16-75		

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1035	CECO Power Turbine Governor Flushing Procedure to Remove Suspected Internal Contamination	01-16-75		
1036	Model 250 Reporting	02-20-75	8	02-07-11
1037	Power Turbine (N ₂) Rub	Cancelled-Ref: Ops. And Maint. Manual		
1038	CECO Fuel Control Cut-Off Valve Lever Adjustment	03-21-75		
1039	Cleaning of the 250-C20/C20B Bendix AL-AA1 Power Turbine Governor PG Air Circuit	Cancelled-Ref: Ops. And Maint. Manual		
1040	Use of Unapproved Parts, Engines, Major Modules, or Piece Parts That May Have Been in Long Term Storage in Rolls-Royce Commercial Engines	07-10-75	7	02-12-02
1041	Proper Use And Mixture Ratios of Fuel System Icing Inhibitor "PRIST"	09-23-75		
1042	Cancelled Prior to Publication			
1043	Cancelled Prior to Publication			
1044	Noisy 250 Series Engine Fuel Pumps	11-26-75	4	06-08-04
1045	Replacement Interval of Fuel Inlet Filter Strainer in Bendix Fuel Control	Cancelled-Ref: Ops. And Maint. Manual		
1046	Model 250 Bendix Fuel System Certified Installation Kits	01-30-76	3	06-01-79
1047	CECO MC-40 Fuel System <u>Daily</u> Deceleration Check	Cancelled-Ref: Ops. And Maint. Manual		
1048	250 Compressor Erosion Inspection	Cancelled-Ref: Ops. And Maint. Manual		
1049	Troubleshooting The Start Derich System On Bendix 250-C20/C20B	Cancelled-Ref: Ops. And Maint. Manual		
1050	250-C20C Engine Time Between Overhauls	Cancelled		
1051	250-C20C Engine Life Limited Parts	Cancelled		
1052	Oil Foaming And Oil Pressure Fluctuations	03-09-78		
1053	Auto Reignition Control Box Assembly	06-30-76		

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1054	Engine Operating Procedures	Cancelled-Ref: Ops. And Maint. Manual		
1055	Gearbox, Wet Spline Starter-Generator Gearshaft (Customer Option)	03-31-78		
1056	Field Cleaning Procedure Relative to Carbon Caused Turbine N ₂ Lockup. All Series I and II Model 250 Engines	Cancelled-Ref: Ops. And Maint. Manual		
1057	Five Micron Low Pressure and High Pressure Filter Elements-Approved Sources	01-14-77		
1058	Increase Of Measured Gas Temperature (TOT) Starting Limit	Cancelled-Ref: Ops. And Maint. Manual		
1059	Fuel System Tubing - Recommended Scheduled Inspections	10-29-76		
A-1060	Power Turbine Outer Coupling Nut Inspection	10-27-76	5	07-22-94
1061	Fuel System - Installation of High Pressure Fuel Filter Assembly	03-31-78		
1062	Engine N ₂ Operating Speed Recommendation	Cancelled-Ref: CEB-A-1174		
1063	Part Number 6853282 and 6887113 Third-Stage Turbine Wheel Replacement Schedule for Casting Sub-surface Porosity	Cancelled		
1064	100 Hour Cleaning of the 250-C20B Lubrication System	Cancelled-Ref: Ops. And Maint. Manual		
1065	Model 250-C20 Series Engine Idle Speed Setting for Engines Equipped with P/N 6887113 or 6888633 Third- Stage Turbine Wheels	Cancelled-Ref: CEB-A-1174		
1066	Part Number 6887113 and 6888633 Third-Stage Turbine Wheel N ₂ Operating Restriction and Alternatives - Overview	Cancelled-Ref: CEB-A-1174		
1067	250-C20/C20B Bendix DP-N ₁ /N ₂ Fuel Control Air Circuit-Field Cleaning	Cancelled-Ref: Ops. And Maint. Manual		
1068	250-C20/C20B Bendix DP-N ₁ /N ₂ Fuel Control P _R -P _G Valve Assembly-Field Cleaning	Cancelled-Ref: Ops. And Maint. Manual		
1069	DDA Model 250 Customer Questionnaire	Cancelled		

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1070	Application of Sealing Compound to the Nozzle Of The Compressor Bleed Valve Assembly	Cancelled-Ref: Ops. And Maint. Manual		
1071	Compressor Case Bolt Tightening Sequence	Cancelled-Ref: Ops. And Maint. Manual		
1072	250-C20F Engine Time Between Overhauls	Cancelled-Ref: Ops. And Maint. Manual		
1073	250-C20F Engine Life Limited Parts	Cancelled-Ref: Ops. And Maint. Manual		
1074	Inspection of <u>FACET</u> Low Pressure Fuel Filter Element (DDA P/N 6895177; Kit P/N 6895028)	Cancelled		
1075	Cancelled Prior to Publication			
1076	Turbine To Compressor Coupling	Cancelled-Ref: Ops. And Maint. Manual		
1077	Cancelled Prior to Publication			
1078	Compressor Case Stator Vane To Rotor "Rub"	03-30-79		
1079	High Pressure Fuel Filter (CECO Fuel System)	Cancelled-Ref: CEB-A-1095		
1080	Model 250/225 Fuel System-Operational and Maintenance Guidelines	05-11-79	2	11-01-88
1081	Air Purge of Low Pressure (LP) Fuel Filter for Single Element Fuel Pumps on Boost Pump Equipped Aircraft	Cancelled-Ref: Ops. And Maint. Manual		
1082	Lubrication System Troubleshooting	06-07-79	7	09-14-09
1083	Use of Silicone Base Molybdenum Disulphide and Nickel Base Anti-Seize Compounds	07-06-79	2	02-15-80
A-1084	Third-Stage Turbine Wheels, Full or Center Slot Blade Shroud Configuration, Replacement After Hot Start-Series II Engines	07-15-79	4	09-01-94
1085	Recall of "PRIST" Packaged in Cans Manufactured By Continental Can Company	Cancelled		
1086	Cancelled Prior to Publication			
1087	Purchase of Detroit Diesel Allison Commercial Model 250 Engines	07-12-79		

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1088	Fuel Pump Filter By-Pass Valve-Periodic Operational Check	Cancelled-Ref: Ops. And Maint. Manual		
1089	Oil System Inspection and Maintenance Requirements on Model 250-C20B, C20F, B17B, and B17C Engines	Cancelled-Ref: Ops. And Maint. Manual		
1090	Fire Extinguisher Material (Cleaning)	09-28-79	1	12-01-80
1091	Fully Slotted Third-Stage Turbine Wheels, P/N 6887113	Cancelled-Ref: CEB-A-1174		
A-1092	Engine Flameouts Due to Snow or Ice Ingestion - Warning	09-15-80	3	10-06-05
1093	Engine Oil Change Time Interval	Cancelled-Refs: Ops. And Maint. Manual		
1094	Bendix Gas Producer Turbine Fuel Control and Power Turbine Governor "Stiff" Throttle Controls	07-30-80		
1095	Special Inspections for Engines Operated in Volcanic Ash	06-02-80	5	01-05-07
1096	Compressor Case-Sealing of Cracked Plastic Liner	Cancelled-Ref: Ops. And Maint. Manual		
1097	Engine N ₁ Ground Operation and Speed Restriction	Cancelled-Ref: CEB-A-1174		
1098	Sundstrand Grease Part Number Change	08-18-80		
1099	Compressor Water Rinse On Engines with Water-Alcohol Augmentation System Installed	07-30-80		
1100	Fuel/Control System Air Leak Safety Warning	09-15-80	2	11-22-10
1101	Flight in Turbulence - Safety Warning	09-30-80		
1102	Heavy Maintenance Inspection Compliance - Optional Gas Producer Turbine Replacement	Cancelled		
1103	Spectrographic Oil Analysis Programs (SOAP) Versus Magnetic Drain Plug Lights-Safety Warning	09-30-80	3	11-01-96
1104	Cancelled Prior to Publication			
1105	Model 250 Series Engine Identification	Cancelled 04-07-08		
1106	Cancelled Prior to Publication			
1107	Turbine "U" Ring Installation And Pressure Test	Cancelled-Ref: Ops. And Maint. Manual		

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1108	List of Model 250 Publications Indicating the Latest Revision as of March 30, 1982	Cancelled		
1109	Cancelled Prior to Publication			
1110	250-C20J Engine Time Between Overhauls	Cancelled-Ref: Ops. And Maint. Manual		
1111	250-C20J Engine Life Limited Parts	Cancelled-Ref: Ops. And Maint. Manual		
1112	Inspection of No. 6 And 7 Bearing Pressure Oil Nozzle after Removal	Cancelled-Ref: Ops. And Maint. Manual		
1113	250 Series II Plugs for Bleed Air Port of Compressor Scroll	12-15-83	1	02-29-84
1114	Cancelled Prior to Publication			
1115	Cancelled Prior to Publication			
1116	Cancelled Prior to Publication			
1117	Cancelled Prior to Publication			
1118	Benefits of an External Scavenge Oil Filter	08-01-84	2	07-28-05
1119	TBO Extension Program, 250 Series Engines	09-14-84	3	04-30-96
1120	Model 250 Rework Parts Policy	Cancelled		
1121	Commercial Engine Bulletin Distribution	07-13-84		
1122	Returning of CEB Compliance Sheets with 250 Engine Module to be Repaired	12-01-85	1	08-07-98
1123	Commercial Engine Bulletin Classification	06-16-86	4	06-19-19
1124	Cancelled Prior to Publication			
1125	Model 250 Alignment Build Procedures	12-01-85	1	05-27-86
1126	Guidelines for Operation of "On Condition" Modules	04-01-88		
1127	Identification of Allison Power Parts (APP)	08-01-85	1	01-31-90
1128	Cancelled Prior to Publication			
1129	Allison Recommended Bulletin Compliance for Turbine Reliability	09-30-85		
1130	Field Vibration Test Procedure	10-17-86	10	06-19-19

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1131	Cancelled Prior to Publication			
1132	Model 250 Module Serial Number Assignment	07-15-86		
1133	Return of Parts for Field Investigation at Allison or Allison Authorized Maintenance Centers (AMC)	04-20-86	2	10-01-96
1134	Correction of Typographical Error in the Log Book CEB List Turbine S/N CAT 24028 And Up	06-16-86		
1135	Contamination Removal (Water Rinse) Instructions <u>Using Water Only</u>	06-23-86	11	12-20-19
1136	Publication Authorization Procedures	11-03-86	5	11-01-96
1137	Alert Document Compliance	01-31-87	3	10-01-96
1138	Allison 250-C20R Series Engine Designations and Conversion Bulletin Information	04-01-87	2	08-01-91
1139	Longer Life Igniter Plugs	08-20-87	3	10-01-96
1140	Chafe Wrapping of Stainless Steel Tube Assemblies	05-01-88		
1141	Warning Tags Attached to Fuel, Oil, Air Tubes, Fittings and Associated Components on 250 Series Engines	09-10-87	2	09-26-00
1142	Guidelines for Operation of Manually Activated Fuzz Burning Engine Chip Detectors	11-01-88		
A-1143	Operational Warning-Height Velocity Diagram (Not a Restriction Nor a Limitation)	Cancelled 07-18-06		
1144	Cancelled Prior to Publication			
1145	Warning-Use of Proper Compressor Scroll To P _c Filter Tube Assemblies	05-01-88		
1146	Serial Number Effectivity, Allison Commercial Engine Bulletins	05-01-88		
1147	Commercial Engine Bulletin Incorporation Philosophy	04-30-88		
1148	Installation of New Gas Produces Tiebolt Nut, P/N 23039751	Cancelled		
1149	Rolls-Royce Customer Training	08-01-88	21	05-27-15
1150	250 Series I and II Coated Compressor Wheels	08-01-88	1	04-01-89
1151	Cancelled Prior to Publication			
1152	Cancelled Prior to Publication			

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1153	Translation of Allison Technical Publications into Foreign Languages	11-01-88		
1154	Use of Eastern European, United Kingdom, and Peoples Republic of China Specification Fuels in Rolls-Royce M250 Engines	04-01-89	7	03-26-14
A-1155	Use of Salvaged or Scrapped Parts in Allison Model 250 Engines	12-01-88	1	08-15-91
1156	Auto Relight Kit Availability	12-01-88		
1157	Cancelled Prior to Publication			
1158	Cancelled Prior to Publication			
1159	Seal Shelf Life (Age Control)	05-01-89	1	08-22-11
1160	Operation of Bendix Fuel Controls and Power Turbine Governors Exposed to Fire or Severe Overtemperature	04-14-89		
1161	Engine Tube Inspection, Aircraft Equipped with Aero Engineering Air Conditioning	05-01-89		
1164	Purolator/Facet External Scavenge Oil Filter Inspection	02-01-90	3	05-03-10
1165	Heavy Maintenance Inspection (HMI) Compliance Option A	Cancelled		
A-1166	Maintenance Warning - External Lines	11-15-90	2	07-08-19
1167	Allison Auto Reignition Control System	12-31-89		
1168	Model 250 Logbook Changes	11-15-94		
1169	N ₂ /N _R Speed Setting	03-15-92		
1170	Model 250 Engine Designations and Applications	11-30-91	5	07-13-15
1171	Model 250 Engine Mean Time Between Removal Experience and Recommendations on use of Overhauled First-Stage Turbine Nozzles	01-31-91	2	05-30-94
1172	Compressor Case, Blade and Vane Erosion/Corrosion Inspection	02-28-91	5	05-20-13
1173	"B" Nut Warning Placard	Cancelled		
1175	Cancelled Prior To Publication			
1176	Optimized Start Technique for Allison 250-C20 Series and C20R Series Engines	12-15-92		
1177	"Premature Engine Removals due to Metal Generation from the 2 1/2 Bearing"	04-30-93		

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1178	Unapproved Hot Engine Cool Down Procedure	03-01-93	1	11-13-01
1179	Recommendations in Conjunction with Engine Oil Change	04-30-93	1	04-15-98
1180	Operation and Maintenance Manual Publications Concerning Magnetic Chip Detector Guidelines	04-30-93		
1181	Authorized Allison Repair/Overhaul Facilities for the Allison Model 250 Engine	Cancelled-Ref Ops & Maint Manual		
1183	Change in Commercial Engine Bulletin Index Format	06-15-93		
A-1186	Inspection, Rework, and Overhaul of Parts Manufactured by Anyone Other Than Allison and/or Allison Approved Vendors and Suppliers	02-15-94	1	11-30-94
1187	Model 250 Power By The Hour®/Fleet Hour Agreement Program	09-30-94	6	Cancelled 02-22-08
1188	Handling of Fluorocarbon Elastomer Preformed Packings and/or Seals	02-01-95		
1189	Allison Model 250 Engine Customer Support and Service Parts Telephone Numbers	Cancelled 02-01-02		
1190	Cancelled Prior to Publication			
1191	Use of Rolls-Royce Military Surplus Parts in Commercial Engines	01-27-95	5 Reissue	04-23-02
1192	Troubleshooting Guide for Bendix Fuel Control Systems Used on Helicopters	06-30-97		
1193	Recommended Use of Airframe Accessory Filter for Remote Area Fueling	09-15-97		
1195	Identification of A New Fuel Pump Vendor	11-01-95	1	06-30-97
1196	Optional Removal or Installation of Compressor Discharge Tube to Fireshield Packing	05-15-97		
1197	Model 250 Publications Procurement Policy	02-15-96	3	03-03-08
1198	Letterhead, Model 250 Commercial Engine Bulletins, Commercial Service Letters and Installation Bulletins	11-15-95		
1199	Manufacturing Origin Request Procedure	02-20-96	3	07-23-04
1200	Brokering of Rejected Series II Compressor Wheels	09-15-96		
1201	Rolls-Royce Part or Assembly Modification	07-31-96	2	05-22-02
1202	No-Go Gages for Spline Inspection	11-15-97	Cancelled	02-10-14

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1204	Disposition of Old Engine and Module Data Plate	10-15-97	3	02-24-16
1205	Return of Model 250 Field Parts for Investigation at Rolls-Royce	06-30-97	4	04-06-15
1207	Commercial Engine Bulletin, CECO Fuel Pump Spline Inspection	09-02-97		
1208	Use of High Thermal Stability (HTS) or Third Generation Oils	09-15-97	2	02-13-12
1209	Commercial Operation of Military T63 Engines	04-30-98	2	10-12-09
1210	Hot Corrosion - Sulfidation	02-10-00	1	05-25-04
1211	Inconel Bellows Incorporation in All 250 AlliedSignal (Bendix) Fuel Controls	02-27-98		
1213	OEM Engine Warranty	04-15-99	1	07-08-16
A-1217	Model 250 Engine Cautions For Changes In Engine Noise	09-15-99		
1218	Alternate Consumable Materials List	04-19-00	3	09-17-12
1219	Rolls-Royce Model 250/Aviall Parts And Technical Publication Distribution	Cancelled 01-25-02		
1220	Manufacturing Tooling Marks On Tubing Assemblies	04-11-00	1	04-27-09
1221	Model 250 Lip Seals	09-07-00	3	05-16-14
1222	Engine - New Publications Prices	08-01-00	1 Reissue	08-24-00
1223	Installation of The Enhanced Power Turbine Kit Hardware, Series II Turboshift Engine	11-28-00		
1224	Special Pricing For 1st-stage Nozzle Shield	Cancelled 07-18-06		
A-1225	Honeywell Extension Of Inconel Bellows Special Pricing	12-20-00		
1226	Second Stage Nozzle Special Pricing Policy	Cancelled 03-15-10		
1228	Black Oxide Removed From Specified Gears	04-05-01	1	04-08-03
1229	Use Of AN503-8-8 Screws In Honeywell Products	04-25-01		
1230	Operations In Methane Laden Atmosphere	09-19-01		
1231	Handling Instructions For Bare Metal Parts	09-19-01	1 Reissue	10-19-01

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1232	Shipment Of Fuel System Components	11-15-01		
1233	Rolls-Royce Model 250 Engine Customer Support And Service Telephone Numbers	Cancelled 03-20-08		
1234	MTU Manufactured Parts	01-08-02	1	02-02-17
1235	Fuel System Contamination	04-23-02	2	07-20-09
1236	Compressor Splined Adapter Wear	01-13-03	1 Reissue	01-22-03
1237	Overhaul Manual MPI Requirements	01-13-03	1 Reissue	01-22-03
1238	Gearbox Bore Alignment Check	05-02-03	1	08-27-04
1239	Position Statement On Use of Red Dye Contaminated Fuel	02-27-03		
1240	Goodrich Pump and Engine Control Systems, Inc. (GPECS) AOG Hotline	08-26-04	1 Reissue	09-17-04
1242	250 Engine Wash Procedures	05-27-04		
1243	Cancellation Notice - Cancellation of AMC-OIL's and AMC-IL's	05-13-04		
1244	Power Turbine Rotor Clamping	05-10-04		
1245	Inspection for Engine Damage Following Failure of Non-Rolls-Royce Provided Engine Hardware	05-26-04	1 Reissue	06-23-04
1247	Model 250 E-Pubs Technical Publications	Cancelled 03-20-08		
1248	Improved Honeywell Power Turbine Governor Program	Cancelled 01-05-09		
1249	Suspect Repairs	10-31-05		
1251	Oil Filter Cap	10-12-07		
1252	M250 Engine Warranty Guidelines	11-15-06	2	07-27-16
1253	Maintenance of Turbine Oil Check Valve	02-07-07	1	09-07-09
1254	Quick Disconnect Magnetic Plug Installation	02-07-07	1	11-17-15
1255	Release of New Blisk Compressor Wheels	03-01-07		
1257	Rolls-Royce Model 250 Fleet Hour Agreement Program	Cancelled 10-07-09		
1260	Rolls-Royce use of Self Adhesive Labels on Certain Parts	06-30-08		

M250-C20 INDEX

Rolls-Royce

COMMERCIAL SERVICE LETTER INDEX

<u>CSL No.</u>	<u>Title/Description</u>	<u>Date Published</u>	<u>Revision Number</u>	<u>Date Revised</u>
1261	Rolls-Royce Model 250 Series II Engines Compressor Shafting Reminder	05-01-09		
1262	TOTALCARE Comprehensive Maintenance Solution for the M250 Engine	10-07-09		
1263	Jet A-1 Fuel System Icing Inhibitor (FSII) Notice	07-26-10		
1264	Rolls-Royce M250® Power Turbine Governor Assembly Replacement Reminder	03-21-11	1	11-11-16
1265	Helicopter Wreckage in Brazil	08-06-12		
1266	AD Note 2012-14-06 AMOC	08-06-12		
A-1267	No. 2 Bearing Installation Information	03-04-13	1	03-24-14
A-1268	Enhanced Awareness of Outer Combustion Cracks (OCC)	03-04-13		
1269	Release of New Accessory Seals	03-24-14	4	01-05-16
1270	New Directional PTO Seal Installation (For Single Lip Seal Engines Only)	08-08-14		
1271	Engine Control System- Identification Plate Change	08-24-15		
1272	Outer Combustion Case Leak TEC Inspection Video	10-19-16		
1273	Release of B-Nut Tool (23083893) and Definition	10-24-16		
1274	Electronic Availability of Commercial Service Letters	02-14-17	1	09-14-18
1275	Engine Assembly- Parts Mutilation Manual	10-17-17		
A-1276	First Stage Turbine Wheel Failure Followed By Inflight Power Loss Due to Over-Temperature Engine Operation	12-05-17		
A-1277	Enhanced Awareness of Loose or Broken Split Line Bolts/Studs	02-09-18		
1278	Engine Preservation and Storage	04-24-19		
1280	Engine- Radiosotopes	11-07-19		
1281	Oil Pressure Regulating Valve Adjustment	12-12-19		